

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NM060-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. LC-055546
2. NAME OF OPERATOR MERIDIAN OIL INC.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 51810, Midland, TX 79710-1810	3a. AREA CODE & PHONE NO. 915-688-6906	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface K, 1980' FSL & 1980' FWL		8. FARM OR LEASE NAME WELLS FEDERAL
		9. WELL NO. 3
		10. FIELD AND POOL, OR WILDCAT JALMAT-TANSIL-YATES-7R
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 4, T-25-S, R-37-E
14. PERMIT NO. 30-025-11441	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3195'GR	12. COUNTY OR PARISH LEA
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

NOTICE OF INTENTION TO PLUG AND ABANDON

Call the BLM prior to commencing plugging operations.

1. MIRU PU. Kill well with water. ND wellhead, NU BOP. POOH with tubing. RIH with casing scraper to $\pm 2950'$, POOH. Set CIBP on wireline at $\pm 2935'$. Spot a cement plug at 2610' - 2935' (35 sxs). Pull up above plug and circulate hole with 9 ppg gelled brine. TAG PLUG
2. Pull up to 1500' and set a cement plug at 1065' - 1500' (45 sxs). Pull up to 50' and circulate cement to surface. Both plugs should be class C cement containing 2% CaCl_2 .
3. Cut off casing 3' below ground level and install P&A marker. Clear and restore location.

18. I hereby certify that the foregoing is true and correct

SIGNED <u>Maria L. Pers</u>	TITLE <u>PRODUCTION ASST.</u>	DATE <u>2-10-92</u>
-----------------------------	-------------------------------	---------------------

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 2/11/92
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side