	[]					Form C-103	
NO. OF COPIES RECEIVED	┟╾╌┍╼╌┤					Supersedes Old C-102 and C+103	
DISTRIBUTION	↓↓┥		VICO OU CONSE	RVATION COMMISSION		Effective 1-1-65	
SANTA FE	↓ ↓	NEWME	XICO DIE CONSE				
FILE	<u> </u>				50	I. Indicate Type of Lease	
U.S.G.S.						State Fee	X
LAND OFFICE					5	State Oil & Gas Lease No.	
OPERATOR							
							\overline{m}
(DO NOT USE THIS FO	SUNDRY	NOTICES AND	REPORTS ON A	NELLS ck to a different reservoir. proposals.)))))
1.	APPLICATION	POR PERMIT - ()			7	. Unit Agreement Name	
OIL GAS		OTHER. Gas	- Oil D _{ual}				
WELL WEL					8	, Farm or Lease Name	
	tion]	Learcy McBuffington	L
Gulf Oil Corpora	101011		<u></u>			. Well No.	
Box \$70, Hobbs, New Mexico 88240						3	
Box \$70, Hobbs,	New Mexi	1.00 00240				0. Field and Pool, or Wildcat	
4. Location of Well	6.64	`	South	1980 F	ปา	u stis Glorieta & Ju	stis
UNIT LETTER	,	J FEET FROM	A THE	LINE AND FE	ET FROM	44 <i>448841111111</i>	119
			05 (27 F	5		1111
THE East	LINE, SECTION	13	OWNSHIP	5	_ NMPM.		\overline{III}
hannen	mm	15 Elevo	ition (Show whether	DF, RT, GR, etc.)		12. County	111
\mathcal{L}	HHHH			3 [†] GL		Lea	$\overline{\eta}$
		<u></u>			or Othe	r Data	
10.			. 10 Indicate N	ature of Notice, Report		REPORT OF:	
NOTI	ICE OF IN	TENTION TO:		SUBSE	QUENT		
-					<u> </u>	ALTERING CASING	
PERFORM REMEDIAL WORK	<u> </u>	PLU	G AND ABANDON	REMEDIAL WORK		PLUG AND ABANDONME	
TEMPORARILY ABANDON	_			COMMENCE DRILLING OPNS.	┝╼┥		استينا ``
PULL OR ALTER CASING		CHA	NGE PLANS	CASING TEST AND CEMENT JQB	╘───┙		
		. –		OTHER			
OTHER Abandon Ju	<u>stis Glo</u>	<u>rieta & Jus</u>	tis Ell				
& recomplete in	Justis	Tubb Drinka	rd.	ile and sive partipant dates i	including e	stimated date of starting any pr	oposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incl work) SEE RULE 1103.

8183' TD, 7935' PB.

Pull producing equipment. Set DR plug in Baker Model D packer at 7764' and cap with 10' (16.5 gallons) of cement. Set CI BP at 6040' and cap with 10' (16.5 gallons) of cement. (10.) gallons) of cement. Set of BF at 0040; and cap with 10. (10.) gallons) of cement. Squeeze Justis Glorieta perforations 4752! to 4802! with approximately 150 sacks of cement. WOC 12 hours. Clean out to 6025!. Test squeezed perforations and BP with 1000#, 30 minutes. Perforate Justis Tubb Drinkard zone in 7" casing with 4, 1/2" JHPF at 5774-76!, 5799-5801!, 5822-24!, 5846-48!, 5938-40! and 5967-69!. Treat new perforations with 9000 gallons of 15% NE acid. Flush with water. Swab and clean up and return well to production.

18. I hereby certify that the information	above is true and complete to the best of my knowledge and belief.	
ORIGINAL SIGNED I C. F. KALTEYE	BY	DATE October 18, 1971
Orig. Si Joe D.		OCT 19 1971
APPROVED BY Dist. L	Supr.	

RECEIVED

001 10 1971

OIL CONSERVATION COMM. HOBBS, N. M.