NO. OF COPIES RECEIVED				Form C-103	
DISTRIBUTION				Supersedes (C-102 and C	102
SANTA FE	NEW MEXICO OIL C	CONSERVATION	Assatifice o. (C. C. Effective 1-1	-103
FILE			•		
U.S.G.S.	3-NMOCC MAY 3 11 O1 AM			State Fee Fee	
LAND OFFICE	l-File				
OPERATOR]			5. State Oil & G	as Lease No.
(DO NOT USE THIS FORM FOR USE "*APPL	IDRY NOTICES AND REPORTS	ON WELLS LUG BACK TO A DIFFERENT R SUCH PROPOSALS.)	RESERVOIR.		
1. OIL GAS WELL WELL	OTHER. Water Inject	tion		7. Unit Agreeme	nt Name
2. Name of Operator Tidewates	ame of Operator Tidewater Oil Company			8. Farm or Lease Name Justis McKee Unit	
3. Address of Operator Box 249,	Hobbs, New Mexico			9. Well No. 612	
Location of Well			10. Field and Pool, or Wildcat		
UNIT LETTER,	1650 FEET FROM THE South LINE AND 990 FEET FROM			Justis McKee	
	ECTION TOWNSHIP	25 S RANGE	37 B		
		ether DF, RT, GR, etc.) 8 DF		12. County Lea	
^{16.} Chee	ck Appropriate Box To Indica	te Nature of Notice	e. Report or Ot	her Data	
	F INTENTION TO:		-	T REPORT OF	:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTE	RING CASING
TEMPORARILY ABANDON		COMMENCE DRILLIN	IG OPNS.	PLUG	AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND C	EMENT JOB		 -1
	lual Blinebry Oil injection well	OTHER			L

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well is presently producing from the Blinebry Oil zone as Gulf Oil Corp's Learcy McBuffington #12. It is proposed to recomplete as a dual oil-water injection well as follows: Kill tubing and casing with IMC inverted emulsion mud. Drill up cement and bridge plug at 5644', clean out to 7185', drill up cement (7185 to 7230') clean out to 7628', drill up cement (7626-7728'), clean out to cement plug at 8290'. Run 4-1/2" ll.6# casing liner (850'), bottom at 7900, top of 7050', cement with 250 sacks neat, reverse out and WOC 24 hours. Drill out cement and test liner. Perforate 4-1/2" liner with one JSFF at 7681-7734 (Zone I), 7750-7777' (Zone II), and 7796-7815 (Zone III). Run treating packer and RBP on bottom, set RBP at 7860', pick up and spot acid across Zone III perforations. Set packer at 7785', acidize with 500 gals 15% with additives to prevent clay swelling, using ball scalers. Swab back acid. Treat with 60# Aquaness 812 and 30% caustic soda mixed in 145 bbls. brine. Zone I and II perforations to be treated same as above. Release packer, pick up RBP and pull out of hole. Run 2-3/8" 8R IFC tubing with Baker's Low-set packer with one joint tail pipe, with Baker's parallel string anchor 2040' above packer. Circulate out mud back to bottom of Blinebry, set packer at 7600'. Run 2-3/8" 8R J-55 tubing with bevelled collars, with J-latch anchor nipple, perforation nipple and seating nipple. Swab mud from Blinebry zone and swab to flowing.

Original Signed By G. L. WADE	Area Supt.	DATE 5-2-66
	TITLE	DATE