· · · · · · · · · · · · · · · · · · ·	-	N.M. OIL CONS. COMMISSION
Form 3160-5 UNIT	LD STATES	P.O. X 1980 HOBBS, NEW MEXICIPITAL No. 1004-0135 Frontes: March 31 1993
	OF THE INTERIOR	HOBBS, NEW President No. 1004-0135 Expires: March 31, 1993
BUREAU OF L	5. Lease Designation and Serial No.	
SUNDRY NOTICES AND	NM-051998	
Do not use this form for proposals to drill of	6. If Indian, Allottee or Tribe Name	
• •	PERMIT - " for such proposals	
SUBMIT	7. If Unit or CA, Agreement Designation	
1. Type of Well Qil Well Gas Well Other	8. Well Name and No.	
2. Name of Operator	SOUTH JUSTIS UNIT"G" #16	
ARCO Permian 3. Address and Telephone No.	9. API Well No. 30-025-11579	
P.O.BOX 1610, MIDLAND, TX 7970	10. Field and Pool, or exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey De	JUSTIS BLBRY-TUBB-DKRD	
2310 FNL & 1980 FEL(UNIT LET	11. County or Parish, State	
13-25S-37E		LEA NM
	TO INDICATE NATURE OF NOTICE	
12. CHECK APPROPRIATE BOX(S		
	[ <sup>1</sup>	
X Notice of Intent	Abandonment Recompletion	Change of Plans New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
		Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X Other ADD PERFS	& TREAT Dispose Water (Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drilled
give subsurface locations and measured and true ver PROPOSE TO: 1. CO TO PBD 5980. 2. RUN GR-CPNL-CCL F/ PBD TO 3. ADD B-T-D PERFS. 4. ACID TREAT. 5. RIH W/ CA.	4500.	rk.)*
14. I hereby certify that the foregoing is true and correct Signed <u>Ken W Gonell</u> (This space for Federal or State office use) Approved by <b>(ORIG. SCD.) JOE G. L</b> Conditions of approval, if any:	Title AGENT	Date 03-24-95

.....

## **WORKOVER PROCEDURE**

**DATE:** March 10, 1995

WELL & JOB: SJU G-16		DRILLED: 1958				
LAST WORKOVER: 8/74 Downhole Commingle		FIELD: Just	is COU	COUNTY: Lea, NM		
BY: W.C. Heard	W. C. Heard <b>TD:</b> 8870'		<b>PBD:</b> 5985'	DAT	<b>'UM:</b> 10' KB	
CASING: SURFACE: INTERMEDIATE: PROD:	<b>SIZE</b> 13-3/8" 9-5/8" 5-1/2"	<u>WEIGHT</u> unk unk 17#	<u>GRADE</u> unk unk unk	<u>SET @</u> 436' 3441' 8774'	<u>SX CMT</u> 450 1895 1250	TOC surf-circ surf-circ 3800'-calc
PERFORATIONS: <u>O</u> 4959-4995'	pen perfs: Blineb	r <u>y 5063-5449' (70</u>	holes), Tubb-Dr	inkard 5772-5978	' (37 holes); plugg	ed perfs: Paddock
TUBING: SIZE: 2-1/ MISC:	'16" <b>WEI</b>	GHT: 3.25# G	RADE: J55	<b>FHREAD:</b> IJ 10	rd JOINTS	<b>BTM'D@</b> ?

HISTORY AND BACKGROUND: During workover of 8/74, cleaned out to 5980' and commingled Blinebry and Tubb-Drinkard. No record of any workovers done since 8/74. (Note: check Production files to verify CA)

SCOPE OF WORK: Add perfs, acidize new and old perfs.

## PROCEDURE

1. MIRU, pull CA.

2. TIH with bit on work string and clean out to 5980'. POH.

- 3. RU WL and run GR-CPNL-CCL from PBD to 4500'. Perforate as per Engineering recommendation.
- 4. Acidize old and new perfs as per attached treatment procedure using packer and BP's (CI or retrievable). POH.
- 5. Run CA as per Production Department design and TOPS.

W. C. Heard J. E. Shields



