Form 9-331 (May 1963)	U T [∞] DEPARTMENT	STATES THE INTERIO	SUBMIT IN THE ICATE (Other Instruct. a one FRIOR verse side)		Form approved. Budget Bureau No. 42-R1424. 5. hease designation and Berial No.		
		SICAL SURVEY	¥ (,		0140978		
			NI WELLS	6. IF I	NDIAN, ALLOTTEE	OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)						<u>.</u>	
. (Do not use	Use "APPLICATION FO	R PERMIT—" for such pro	oposals.)		T ACREEMENT NA	(E	
1. Q16 C GAS C					Langlie-Jal Unit		
WELL WELL OTHER Water Injection					M OR LEASE NAME		
2. NAME OF OPERATO		ODATION			٠.	÷ +	
UNION TEXAS PETROLEUM CORPORATION 3. ADDRESS OF OPERATOR					L NO.		
1200 Wilco Building Midland Texas 79701					WIW		
recarion or wert. (Report location clearly and in accordance with any State requirements.					ELD AND POOL, OR	WILDCAT	
See also space 17 below.) At surface					glie-Matti	x (Queen)	
				11. SE	C., T., R., M., OR BI SURVEY OR AREA	LA. AND :	
•		•			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0 10 27 H	
Unit Let	ter "P", 660' FS&E		The state of the s	Sec.	17, T-25-		
14. PERMIT NO.	į	EVATIONS (Show whether DY,	RI, UR, EUC.)			New Mexico	
		200' GR	· · · · · · · · · · · · · · · · · · ·	<u>l Le</u>			
16.	Check Appropria	ite Box To Indicate N	ature of Notice, Report,	or Other D	ata		
	NOTICE OF INTENTION TO:		ສບ	BSEQUENT REI	ORT OF:		
	PERTY OR	ALTER CASING	WATER SHUT-OFF		REPAIRING W	FELL	
TEST WATER SH FRACTURE TREAT	[]	COMPLETE	PRACTURE TREATMENT		ALTERING CA		
SHOOT OR ACIDI	·		BHOOTING OR ACIDIZING	· []	ABANDONMEN	T*	
REPAIR WELL	CHANGE I	PLANS	(Other) (Nore: Report re	fum to ether	tiple completion	on Well	
	an out & Deepen	<u> </u>	Completion of Ke	completion we	short and mos vor	****	
17. DESCRIBE PROPOS	ED OR COMPLETED OPERATIONS	(Clearly state all pertinen illed, give subsurface local	t details, and give pertinent clions and measured and true v	dates, includivertical depth	s for all markers	and zones perti-	
nent to this wo	ork)*			:			
	•			•			
	D.11 tubing and D	ncker					
1.	Pull tubing and pa Clean out to origin	inal TD of 3400'					
3	Deepen well to TD	of 3520' (3-3/4	" hole).	. •			
4.	Log well to TD.	•			g fat		
5. Perforate Seven Rivers Queen Zone.							
6. Stimulate if necessary.							
7.	Run tubing and page	cker.	1 - 1 -				
8.	Place well back or	n injection thru	open noie.				
•	• ,						
•		·					
	t		•				
	ļ						
						•	
**		*				*,	
				•		*	
-					•	• • •	
18 I harahy cartifu	that the foregoing is true a	nd correct					
· ~	to ly A () to	A minute Ga	s Measurement Anal	yst	DATE May	28, 1975	
SIGNED	unery 15. Itil	TILE S					
(This space for	Federal or State office use)	•		J	: .		
APPROVED B	Y	TITLE	+ ATTION		DATE		
CONDITIONS	OF APPROVAL, IF ANY:		00 19	JT5 ///	5		

*See Instructions on Reverse SideR R. DICINEER