NO. OF COPIES RECEIVED		Form C-103 Supersedes Old
DISTRIBUTION		C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		En Indicate Time of Logge
U.S.G.S.		Sa, Indicate Type of Lease State Fee X
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		5. State Off & Gus, Lease No.
		mmmmm -
SUND	ORY NOTICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR ATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
(DO NOT USE THIS FORM FOR PE	ATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7, Unit Agreement Name
l. OIL GAS		7. One Agreement Rune
WELL WELL	OTHER-	8. Farm or Lease Name
2. Name of Operator		
TEXAS PACIFIC OI	L COMPANY	Harner 9. Well No.
3. Address of Operator		5. Well Ivo.
	Hobbe, New Mexico 88240	10. Field and Pool, or Wildcat
4. Location of Well	1005	,
UNIT LETTER	1980 FEET FROM THE South LINE AND 1905	FEET FROM Jalmat
!		
THE LINE, SECT	TION 20 TOWNSHIP 25-8 RANGE 37-E	— имрм. <i>{}}}}}</i>
	15. Elevation (Show whether DF, RT, GR, etc.)	12, County
Öllilli (11111111111111111111111111111111	3045.5' GR	Lea
16. Check	Appropriate Box To Indicate Nature of Notice, Repo	
NOTICE OF	INTENTION TO: SUBS	EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON KEMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOE	
	OTHER	
OTHER		
17 Describe Proposed or Completed	Operations (Clearly state all pertinent details, and give pertinent dates,	including estimated date of starting any proposed
work) SEE RULE 1103.		
Ilyan engravel we	propose to plug and abandon above well as	follows:
obor approvat we	. Propose to Prof. con annual and an	
1. Bisplace wel	1 fluids with mud laden fluid.	
**		
2. Spot 25 sks.	cement over perfs 3170-3274'.	
2, 2,00 20 0000	• • • • • • • • • • • • • • • • • • • •	
3. Spot 25 sks.	cement over perfs 2670-2760'.	
4. Shoot off 7"	esg. at free point (Approx. 2000')	
,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
5. Lay down rec	covered 7" csg.	
3, 22, 20 100		
6. Run open-end	tubing to cut off and spot 25 sk. cemnt pl	lug.
o, man open one		
7. Spot 25 sks.	at 308'-bottom of 9-5/8" csg.	
,, open as ease		
8. Spot 10 sks.	at surface and install dry hole marker.	
o. spot 10 sms.		
9 Fill celler	and clean location.	
18. I hereby certify that the informati	ion above as true and complete to the best of my knowledge and belief.	
Original	Signed by	
	TITLE Area Superintende	DATE 12-23-68
Sheldo	or Ward	
1 //	\mathcal{L}	
John IN.	Kundan TITLE	DATE
APPROVED BY		
CONDITIONS OF APPROVAL, IF A		