

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLE
(Other instructions
reverse side)

B*
re-

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

JUN 23 10 36 AM '91

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PENROC OIL CORPORATION

3. ADDRESS OF OPERATOR

P.O. BOX 5970, HOBBS, NEW MEXICO 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

2310' FSL & 990' FEL

Unit I

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3066 DF

5. LEASE DESIGNATION AND SERIAL NO.

LC-032579-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

HARRISON

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

LANGLEY MATIX (GAS)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC. 22, T. 25S, R. 37E

12. COUNTY OR PARISH

LEA

13. STATE

NEW MEXICO

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9 5/8" CSG @ 1100'. 7" CSG @ 3218 W/ 250 SXS.

OH TD: 3366'

Proposed: Set CIBP @ 3150'. Dump 10 SXS. cement on top. Cut & pull 2100' of 7" CSG.

Spot cement plug 2050' - 2150'. TAG PLUG.

Spot 50 SXS plug @ the base of 9 5/8". TAG PLUG.

Spot 50 FEET 10 SXS plug @ surface.

Install dry hole marker. Clean up location & seed.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

President

DATE

6/21/91

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DEPARTMENTAL ATTORNEY

DATE

7/9/91


NOTIFY BLM AT (505) 393-3612 PRIOR TO COMMENCING PLUGGING OPERATIONS.
PLACE G.O.P.P.Y. MUD BETWEEN PLUGS.

*See Instructions on Reverse Side

HARRISON NO. 2
Sec. 22, T25S, R37E
LEA COUNTY, NM

PRESENT

PROPOSED



RECEIVED

JUL 18 11 20 AM '91

CARTER
AREA

JUL 31 1991

MOBILE