DEPARTMENT OF THE INTERIOR Peres addo: GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to dispens or plage back to a different reservoir. (Do not use this form for proposals to drill or to dispens or plage back to a different reservoir. (Do not use this form for proposals to drill or to dispens or plage back to a different reservoir. (Do not use this form for proposals to drill or to dispens or plage back to a different reservoir. (Do not use this form for proposals to drill or to dispens or plage back to a different reservoir. (OCT OF THE NAME OF TH	Form 9-331 (May 1963)	UNITED STATES	SUBMIT IN TRIPLICATION (Other instructions on the	re- Budget .	Bureau No. 42-R1
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plage back to a different reservoir. 1.	DEP/		IOR verse side)	5. LEASE DESIGNA	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals of offilior to depen or plug back to a different refervoir. (In the "APPLICATION FOR PERMIT—" for such proposals.) 1.		GEOLOGICAL SURVEY			\
ORTHOR OF INTENTION TO: TEST WATER SHOT-OFF SEATOR SHOWER SHOW MENTION ABADON'S SHOWER TREATER THE TERRATE SHOT-OFF SEATOR SHOWER THE TERROSSO OF CONTROL OF SHORE SHOWER TO SHOW THE SHOWER OF SHOWER THE TERROSSO OF CONTROL OF SHORE SHOWER THE TERROSSO OF CONTROL OF SHOWER THE SHOWER THE TERROSSO OF CONTROL OF THE TERROSSO OF CONTROL OF THE TERROSSO OF CON	SUNDRY I (Do not use this form for Use "Al	NOTICES AND REPORTS (proposals to drill or to deepen or plug leptication for PERMIT—" for such p	ON WELLS back to a different reservoir. roposals.)	J. IT INDIAN, ALL	OTTEE OR TRIBE AS
Getty Oil Company A. B. Coates "C" P.O. Box 730 Hobbs, New Mexico 88240 4. Locations of well. (Report location clearly and in accordance with any State requirements.' At surface Unit Letter J., 1980' FSL and 2310' FWL, Sec. 24-T25S-R37E 11. PERMIT NO. 15. RIEVATIONS (Show whether PF, RT, CR. etc.) 12. CONTRO of PARTICLE OF PRICE OF INTENTION TO: TEST WATER SHOT-OFF PELL OR ALTER CASING MULTIPLE COMPLETE ABADON'* CHANGE PLANS CHANGE PLAN	OIL GAS			7. UNIT AGREEMEN	NT NAME
P.O. Box 730 Hobbs, New Mexico 88240 4. Location of well (Report location clearly and in accordance with any State requirements.' See also space 17 below.) Unit Letter J, 1980' FSL and 2310' FWL, Sec. 24-T25S-R37E 11. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 12. COCKTY OR PARISH 13. STATE 13. STATE 14. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 12. COCKTY OR PARISH 13. STATE 14. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 12. COCKTY OR PARISH 13. STATE 14. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 12. COCKTY OR PARISH 13. STATE 14. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 12. COCKTY OR PARISH 13. STATE 14. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 12. COCKTY OR PARISH 13. STATE 14. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 12. COCKTY OR PARISH 13. STATE 14. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 12. COCKTY OR PARISH 13. STATE 14. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 12. COCKTY OR PARISH 13. STATE 13. STATE 14. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 12. COCKTY OR PARISH 13. STATE 13.		нек		S. FARM OR LEAST	NAME
4. Linchtins of with (Report location clearly and in accordance with any State requirements.* See also space IT below.* Unit Letter J, 1980' FSL and 2310' FWL, Sec. 24-T25S-R37E 11. PERMIT NO.					es "C"
4. Ideation or wett. (Report location clearly and in accordance with any State requirements.) 4. Unit Letter J, 1980' FSL and 2310' FWL, Sec. 24-T25S-R37E Unit Letter J, 1980' FSL and 2310' FWL, Sec. 24-T25S-R37E 11. PERMIT NO. 15. REPVATIONS (Show whether pr, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL CHANGE PLANS LOUNDLEAD OR ACIDIZE REPAIR WELL CHANGE PLANS WATER SHUT-OFF PROCTURE TREAT SHOOT ON ACIDIZE REPAIR WELL CHANGE PLANS LOUNDLEAD OR ACIDIZING ABANDON' ABANDON' SHOOT OR ACIDIZING ABANDON' WATER SHUT-OFF PRACTURE TREATHENT ALTERING CASING REPAIR WELL COMPLETED OF PRACTURES (Clearly state all pertinent details, and give pertinent dates, including estimated date of star percended work. If well is directionally drilled, give subsurface locations and measured and true vertical deptits for all markers and x remains to this work.)* Well No. 13 is producing 10 BOPD and 101 BWPD from the Justis Montoya. It is p to squeeze cement the present Lower Montoya perforations and perforate the Upper Mo The workover procedure is as follows: (1) Rig up pulling unit and pull rods and pump. (2) Install BOP and pull tubing. (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt.	P.O. Box 730 Hobbs	New Mexico 88240		13	
Unit Letter , 1, 1980' FSL and 2310' FWL, Sec. 24-T25S-R37E 11. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3086 DF 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHOT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE SHOOT OR ACIDIZE REPAIR WELL ZE LOWER MONTONA and complete in Upper X WATER SHOT-OFF OR ACIDIZE REPAIR WELL ZE LOWER MONTONA OR DEBATIONS (Clearly state all pertinent details, and give retinent dates, including estimated date of state entry to this work.) Well No. 13 is producing 10 BOPD and 101 BWPD from the Justis Montoya. It is p to squeeze cement the present Lower Montoya perforations and pump. (2) Install BOP and pull tubing. (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya perforations 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt.	 LOCATION OF WELL (Report loc See also space 17 below.) 	ation clearly and in accordance with any	State requirements.*		
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACCIDIZE REPAIR WELL CHANGE PLANS CONTRIBUTION TO SHOOTING OR ACCIDIZED REPAIR WELL CHANGE PLANS CHANGE PLANS CONTRIBUTE COMPLETE ABANDON'S SHOOTING OR ACCIDIZED REPAIR WELL CHANGE PLANS CONTRIBUTE COMPLETE TO PRESENT ON A CIDENTING OR ACCIDIZED REPAIR WELL CHANGE PLANS CONTRIBUTE COMPLETE TO PRESENT ON A CIDENTING OR ACCIDIZED REPAIR WELL CHANGE PLANS CONTRIBUTE COMPLETE TO PRESENT ON A CIDENTING OR ACCIDIZED ABANDON'S SHOOTING OR ACCIDIZED ABANDON'S SHOOTING OR ACCIDIZED CONTRIBUTE COMPLETE TO PRESENT OR ACCIDIZED ABANDON'S SHOOTING OR ACCIDIZED CHANGE PLANS CONTRIBUTE COMPLETE TO PRESENT OR ACCIDIZED ABANDON'S SHOOTING OR ACCIDIZED ABANDON'S SHOOTING OR ACCIDIZED ABANDON'S SHOOTING OR ACCIDIZED CONTRIBUTE COMPLETE TO PRESENT OR ACCIDIZED ABANDON'S SHOOTING OR ACCIDITED ACCIDITED OR ACCIDITED ABANDON'S SHOOTING OR ACCIDITED	Unit Letter 🕽, 1980)' FSL and 2310' FWL, Sec	c. 24-T25 S-R37E	11. SEC., T., B., M.	OR BLK. AND
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data Notice of Intention to: TEST WATER SHCT-OFF PULL OR ALTER CASING SHOOT OR ACIDIZE ABANDON* CHANGE PLANS CHANGE PLANS CHANGE PLANS WATER SHCT-OFF PRACTURE TREAT SHOOT OR ACIDIZE ABANDONNENT* CHANGE PLANS CHANGE PLANS CHANGE PLANS WATER SHCT-OFF PRACTURE TREATMENT ALTERING CASING ABANDONNENT* (Other) CHANGE PLANS (Other) CHANGE SHOULD ON ACIDIZING ABANDONMENT* ALTERING CASING ABANDONMENT* (Other) CHANGE SHOULD ON ACIDIZING (Other) CHANGE SHOULD ON ACIDIZING (Other) CHANGE SHOULD ON ACIDIZING ALTERING CASING ABANDONMENT* ALTERING CASING ABANDONMENT* (Other) COTES SHOULD ON ACIDIZING ABANDONMENT* (Othe	14. PERMIT NO.	15. ELEVATIONS (Show whether DE	r, RT, GR. etc.)		
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data Notice of Intention to: TEST WATER SHOT-OFF FRACTURE TREAT SHOOT OR ACIDIZE ABANDON* CHANGE PLANS COMPLETION OF R-completion of multiple completion on Well Practices report results of multiple completion on Well No. 13 is producing 10 BOPD and 101 BWPD from the Justis Montoya. It is p to squeeze cement the present Lower Montoya perforations and perforate the Upper Mo The workover procedure is as follows: (1) Rig up pulling unit and pull rods and pump. (2) Install BOP and pull tubing. (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt.		3086 DF		Lea	N.M
NOTICE OF INTENTION TO: TEST WATER SHOT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON* SHOOT OR ACIDIZE ABANDON* CHANGE PLANS CORPLICION OR ACIDIZING ABANDONNENT' (Other) NOTE: Report results of multiple completion on Well proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and accompletion on the proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and accompletion on the proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and accompletion on the proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and accompletion on the proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and accompletion on the proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and accompletion on the proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and accompletion on the completion on Well proposed work. If well a proposed work if well a proposed work if well and true vertical depths for all markers and accompletion on the completion of the	16. Che		Nature of Notice Report, or	Other Data	
PRACTURE TREAT SHOOT OR ACIDIZE ABANDON* CHANGE PLANS CLOWEN Montoya and complete in Upper X REPAIR WELL CHANGE PLANS CLOWEN Montoya and complete in Upper X Completion or R-completion Report and Log form.) Ad. DESCRIBE PROCESSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of state next to this work.)* Well No. 13 is producing 10 BOPD and 101 BWPD from the Justis Montoya. It is p to squeeze cement the present Lower Montoya perforations and perforate the Upper Mo The workover procedure is as follows: (1) Rig up pulling unit and pull rods and pump. (2) Install BOP and pull tubing. (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt.		, , ,			
SHOOT OR ACIDIZE REPAIR WELL CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS COMPLETE Report results of multiple completion on Well Completion or R-completion Report and Log form.) Ad. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent datas, including estimated date of star proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zo a squeeze cement the present Lower Montoya perforations and perforate the Upper Mo The workover procedure is as follows: (1) Rig up pulling unit and pull rods and pump. (2) Install BOP and pull tubing. (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt.	TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	BEPAIR	ING WELL
REPAIR WELL ZE LOWER Montoya and complete in Upper X Ze LOWER Montoya and complete in Upper X Completion or R-completion Report results of multiple completion on Well Compressed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zero squeeze cement the present Lower Montoya perforations and perforate the Upper Mo The workover procedure is as follows: (1) Rig up pulling unit and pull rods and pump. (2) Install BOP and pull tubing. (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt.	FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERI	NG CASING
Ze Lower Montoya and complete in Upper X (Note: Report results of multiple completion on Well Completion or Recompletion Benott and Log form.) 73. DESCRIBE PROCOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of state proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zo nent to this work.) Well No. 13 is producing 10 BOPD and 101 BWPD from the Justis Montoya. It is possible to squeeze cement the present Lower Montoya perforations and perforate the Upper Montoya perforations and pull produced and pump. (1) Rig up pulling unit and pull rods and pump. (2) Install BOP and pull tubing. (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt.	SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDO	ONMENT*
### Description of R-completion of State of Distance of State on the Upper Model of Recompletion of State of State of State on the Upper Model of Recompletion of State of		; !		lts of multiple comple	tion on Well
Well No. 13 is producing 10 BOPD and 101 BWPD from the Justis Montoya. It is p to squeeze cement the present Lower Montoya perforations and perforate the Upper Mo The workover procedure is as follows: (1) Rig up pulling unit and pull rods and pump. (2) Install BOP and pull tubing. (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt.	1d. DESCRIBE PROPOSED OR COMPLET proposed work. If well is		Completion or Recor	upletion Report and L	og form.)
to squeeze cement the present Lower Montoya perforations and perforate the Upper Mo The workover procedure is as follows: (1) Rig up pulling unit and pull rods and pump. (2) Install BOP and pull tubing. (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt.		producing 10 BOPD and 10	on BWPD from the Jus	tis Montova.	It is prope
 The workover procedure is as follows: (1) Rig up pulling unit and pull rods and pump. (2) Install BOP and pull tubing. (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt. 					
 (2) Install BOP and pull tubing. (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt. 			· · · ·		
 (3) Run cement retainer and set at 6700'. (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt. 			ump.		
 (4) Squeeze Montoya perforations 6854'-7024' with 200 sacks. (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt. 	1 1				
 (5) WOC 24 hrs. (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt. 			with 200 sacks.		
 (6) Drill out retainer at 6700' and cement to 6874'. (7) Test squeeze. (8) Perforate Montoya selectively from 6810'-6856'. (9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt. 		702	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
(8) Perforate Montoya selectively from 6810'-6856'.(9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt.		ner at 6700' and cement o	to 6874'.		
(9) Acidize Montoya perforations 6810'-6856' with 4500 gallons 15% NE HCL acid, 200 benzoic flakes, and 600 lbs. of rock salt.					
benzoic flakes, and 600 lbs. of rock salt.	(8) Perforate Montoy	ya selectively from 6810	'-6856'. with 4500 asllone	150 ME UOL SO	id 200 15
(10) Return well to pumping producing Justis Montoya perforations 6810'-6856'.				TOS HE HUE de	. 1 u , 200 ID
	(10) Return well to r	pumping producing Justis	Montoya perforation	s 6810'-68 56'	•
	(==)				

SIGNED .

APPROVED BY ______CONDITIONS OF APPROVAL, IF ANY:

(This space for Federal or State office use) TITLE HPR 1 4 1978 (1. 4. L. LACTING DISTRICT ENGINEER *See Instructions on Reverse Side