

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dual</u>	7. Unit Agreement Name
2. Name of Operator <u>Amerada Hess Corporation</u>	8. Farm or Lease Name <u>Ida Wimberley</u>
3. Address of Operator <u>Drawer "D", Monument, New Mexico 88265</u>	9. Well No. <u>5</u>
4. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>2080</u> FEET FROM THE <u>West</u> LINE, SECTION <u>25</u> TOWNSHIP <u>25-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Justis</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3073' DF</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Squeeze Tubb-Drinkard zone perforations and abandon Tubb-Drinkard zone.

Squeeze Fusselman zone perforations. Reperforate Fusselman zone at 6748', 6751', 6762', 6778', 6785', 6789', 6795', 6809', 6813', 6821', 6827', 6831', 6835', 6839', 6843', 6847'. Acidize perforations with 6000 gals. 15% NE acid. Rerun production equipment and resume production from Fusselman zone.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED MC [Signature] TITLE Area Production Clerk DATE 4-24-72

APPROVED BY Joe D. Ramey TITLE Dist. 1, Supv. DATE APR 27 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 25 1972

OIL CONSERVATION COMM.
HOBBS, N. M.