

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name B-11478
2. Name of Operator ARCO Oil and Gas Company		8. Farm or Lease Name State "Y"
3. Address of Operator P.O. Box 1610, Midland, Texas 79702		9. Well No. 3
4. Location of well UNIT LETTER <u>B</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>25S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Justis Blinebry/ Montoya
15. Elevation (Show whether DF, RT, CR, etc.)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Downhole Commingle R-8406	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to downhole commingle as follows:

1. RU PU. POH w/CA.
2. Knock Model "D" pkr to PBD.
3. RIH w/RBP & pkr. Set RBP @ 5575' & test to 1000#. Set pkr @ 5050'. PA to 300#.
4. Acidize Blinebry perfs f/5118-5534' w/10,000 gal.
5. POH w/RBP & pkr.
6. RIH w/tbg, rod & pump. Return to Production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kennel Gosnell TITLE Engr. Tech. 915-688-5672 DATE 3-30-87

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT 1 SUPERVISOR DATE APR 2 1987

CONDITIONS OF APPROVAL, IF ANY: