Form 9-331

HALL A STATES

(May	1000/	MILLO STATES	Other instructions on re-	Budget Bureau No. 42-R1424.	
	DEPARTM	ent of the inter	RIOR verse side)	5. LEASE DESIGNATION	ON AND SERIAL NO.
	GEOLOGICAL SURVEY				022570 8
	SUNDRY NOTIC (Do not use this form for proposal Use "APPLICAT	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
1. on wi	L GAS X OTHER	7. UNIT AGREEMENT NAME			
2. NA	AME OF OPERATOR	8. FARM OR LEASE NAME			
	L Paso Natural Gas Componess of Operator	Harrison Federal.			
18	300 Wilco Building, Mic	01	2		
4. LO Se	OCATION OF WELL (Report location clear re also space 17 below.) t surface	10. FIELD AND POOL, OR WILDCAT			
	660 FNL & 660	50.30 67	Jalmat 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
14. PE	GRMIT NO.	15. ELEVATIONS (Show whether	DE DI GD oks	Sec. 27, T-	25-S, R-37-E
		3110 Gr.	pr, ki, Gr, etc.)	12. COUNTY OF PARIS	N. M.
16.	Check App	ropriate Box To Indicate	Nature of Notice, Report, or C		
	NOTICE OF INTENTIO	ENT REPORT OF:			
т	EST WATER SHUT-OFF PUI	LL OR ALTER CASING	WATER SHUT-OFF	REPAIRING	WELL
F	TRACTURE TREAT MU	LTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING	
s	SHOOT OR ACIDIZE ABA	ANDON*	SHOOTING OR ACIDIZING	ABANDONM	ENT*
		ANGE PLANS	(Other)		
	Other)Open Additional Ya	nal Yates Sections X (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
	nent to this work.) *	ny dimed, give subsurface los	ent details, and give pertinent dates, cations and measured and true vertica	including estimated d depths for all mark	ate of starting any ers and zones perti-
PI.	an is to remove wellhe	ad and install BO	P, pull tubing and set	retrievable	bridge

lug at 2865', spot 250 gallons double inhibited HCL acid 2865' to 2715'. Run Gamma Ray Correlation Log and perforate intervals with 1 SPF: 2848-40, 2810-2800, 2780-65. Set packer at 2700' and break perfs down with 2000 gallons 7 1/2 % HCL acid, shut-in 2 hours then swab test through tubing. If additional gas is indicated fracture intervals down tubing in three stages using 10,000 gallons foam plus 16,000# 20/40 sand and 11 ball sealers. Then blow back immediately to clean up. Swab if necessary, pull packer and land tubing at 3050. Rig down, replace wellhead and return well to production.

Proposed starting date: August 3, 1977, subject to unit availability.

18. I hereby certify that the foregoing is true and correct			
SIGNED C. C. Goodwin	TITLE A	dm. Prod.	Service Dark July 14, 1977
(This space for Federal or State office use)		\	1077 (0/1)
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE		JUL 15 1911
			AKIMUR 2. BROWN ARIMUR 2. BROWN ARIMUR 2. BROWN ARIMEE!
		_	MISTRIC

*See Instructions on Reverse Side