

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ALANTA FE	
FILE	
J.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. State Oil & Gas Lease No.
Name of Operator TEXAS PACIFIC OIL CO., INC.		7. Unit Agreement Name
Address of Operator P. O. Box 1069 - Hobbs, New Mexico 88240		8. Farm or Lease Name GUTMAN
Location of Well UNIT LETTER I 1980 FEET FROM THE South North LINE AND 660 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 25 RANGE 37 NMPM.		9. Well No. 1
15. Elevation (Show whether DF, RT, GR, etc.) 3020' GR		10. Field and Pool, or Wildcat Langlie Mattix
12. County Lea		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PLUG OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
---	---	---	---

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in, rig up. Pull tubing.
2. Set CIBP in 7" casing above shoe @ 3130' and spot 25 sxs. cement.
3. Load casing with mud.
4. Spot 10 sxs. cement plug @ surface.
5. Cut off well head and cap with cement.
6. Set dry hole marker and clean location. Cut dead men.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by Sheldon Ward TITLE Area Superintendent DATE 2-1-71
 SIGNED BY [Signature] TITLE [Signature] DATE MAR 3 1971
 CONDITIONS OF APPROVAL, IF ANY: