NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBS OFFICE OCC

Send Communications regarding well to:

Address Box 746, Midland, Texas

Name Jerry Covington

MISCELLANEOUS NOTICES OR M 1:27

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by Checkin	Ig Delow	
Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	Notice of Intention to Plug Back	Notice of Intention to Set Liner	
Notice of Intention to Squeeze	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	Notice of Intention (Other) Fluid Frac	Notice of Intention (Other)	
OIL CONSERVATION COMMIS SANTA FE, NEW MEXICO		February 22, 1955	
Gentlemen:			
Following is a Notice of Inten	cion to do certain work as described below at the	Jerry Covington	•••••
(Company o	r Operator)	Well No. 2 Federal in	(Unit)
NW 1/4 SW 1/4 of Sec	31 , T 25 S , R 37 E ,N	ирм.,Jalmat	Poc
NW 1/4 SW 1/4 of Sec (40-acre Subdivision)		IPM., Jalmat	Poc
(40-acre Subdivision)	County. FULL DETAILS OF PROPOSED PLA	N OF WORK	Рос
Lea (H	FULL DETAILS OF PROPOSED PLA COLLOW INSTRUCTIONS IN THE RULES A	N OF WORK	Рос
Lea (F	FULL DETAILS OF PROPOSED PLA COLLOW INSTRUCTIONS IN THE RULES AS 1500# psi to test casing	N OF WORK	Рос
1. Pressure up t	FULL DETAILS OF PROPOSED PLA COLLOW INSTRUCTIONS IN THE RULES A TO 1500# psi to test casing The pull packer	N OF WORK ND REGULATIONS)	Рос
1. Pressure up t 2. Kill well and 3. Run tubing wi	FULL DETAILS OF PROPOSED PLA COLLOW INSTRUCTIONS IN THE RULES A co 1500# psi to test casing pull packer th perforations and pin coller of	N OF WORK ND REGULATIONS) on bottom	Рос
1. Pressure up t 2. Kill well and 3. Run tubing wi	FULL DETAILS OF PROPOSED PLA COLLOW INSTRUCTIONS IN THE RULES A co 1500# psi to test casing pull packer th perforations and pin collar of the perforations are perforations.	N OF WORK ND REGULATIONS) on bottom	Рос
1. Pressure up to 2. Kill well and 3. Run tubing with 4. Sand frac well perforations	FULL DETAILS OF PROPOSED PLA COLLOW INSTRUCTIONS IN THE RULES A co 1500# psi to test casing pull packer th perforations and pin collar of the perforations are perforations.	N OF WORK ND REGULATIONS) on bottom	Рос
1. Pressure up to 2. Kill well and 3. Run tubing with 4. Sand frac well perforations	FULL DETAILS OF PROPOSED PLA COLLOW INSTRUCTIONS IN THE RULES A co 1500# psi to test casing pull packer th perforations and pin collar of l with 10,000 gals, and 1 ## sand in casing	N OF WORK ND REGULATIONS) on bottom	Рос
1. Pressure up to 2. Kill well and 3. Run tubing with 4. Sand frac well perforations	FULL DETAILS OF PROPOSED PLA COLLOW INSTRUCTIONS IN THE RULES A co 1500# psi to test casing pull packer th perforations and pin collar of l with 10,000 gals, and 1 ## sand in casing	N OF WORK ND REGULATIONS) on bottom	Ρα

Approved

OIL CON

Title.....