STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

| 40. 07 COPIES SCCEIVED | | | |
|------------------------|----|--|--|
| DISTRIBUTION | | | |
| SANTA FE | | | |
| FILE | | | |
| U.S.G.S. | T- | | |
| LAND OFFICE | 1 | | |
| OPERATOR | 1 | | |

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 - Revised 10-1-78

| FILE | SANTA FE, NE | W MEXICO 87501 | . KG41260 IN-1- |
|--|---------------------------------------|---|---|
| U.S.G.S. | | | 5a. Indicate Type of Lease |
| LAND OFFICE | | | State X Fee |
| OPERATOR | | | 5. State Oil & Gas Lease No. |
| SAND DAY NO | T-050 | | |
| SUNDRY NO SUNDRY NO USE THIS FORM FOR PROPOSAL USE THIS FORM FOR PROLICATION FO | DTICES AND REPORTS OF | V WELLS | |
| 1. | R PERMIT - " (FORM C-101) FOR SE | JCH PROPOSALS.) | |
| WELL OF WELL OF | THER- | | 7. Unit Agreement Name |
| 2. Name of Operator | | | 8. Form or Lease Name |
| Chevron U.S.A. Ir | ic. | • | Arnott Ramsay (NCT-F) |
| J. Address of Operator | | | 9. Well No. |
| P.O. Box 670 Hob | bs, NM 88240 | | 10 |
| 4. Location of Well | | | 10. Field and Pool, or Wildcat |
| UNIT LETTER H 1650 | FEET FROM THE North | LINE AND 660 | Justis Blinebry |
| ļ | | | |
| THE East LINE, SECTION 36 | TOWNSHIP | RANGE R37E NMP | |
| mmmmmmm | (6) | | |
| | 15. Elevation (Show whether 3032 GL | DF, RT, GR, etc.) | 12. County |
| 16. | | | Lea AllIIIII |
| Check Appropriate Box To Indicate Nature of Notice, Report or O NOTICE OF INTENTION TO: SUBSEQUEN | | ther Data | |
| | | IT REPORT OF: | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | | |
| TEMPORARILY ABANDON | PLUE AND ABANDON | REMEDIAL WORK | ALTERING CASING |
| PULL OR ALTER CASING | CHANGE PLANS | COMMENCE ORILLING OPHS. CASING TEST AND CEMENT JOB | PLUG AND ABANDONMENT |
| Add linnan Plinakau D | | OTHER | |
| Add Upper Blinebry Per | rforations X | | |
| 17 0 | | | |
| Describe Proposed or Completed Operation work) SEE RULE 1 (03. | s (Clearly state all pertinent deta | ails, and give pertinent dates, includin | g estimated date of starting any proposed |
| MIRU PU. POH with roo | ds, pump, and tubing | . Perforate Upper Blin | ehry from |
| 3001 -3201 . Set KBP | U 5465' LEST TO SIN | Oncil Acidiza and foar | +1110 m +11 = 1 |
| as necessary. Pull RE | 3P after stabilized | test. Return well to pr | oduction. |
| | | · | |
| | | | |
| | | | • |
| | | | |
| | | | |
| | | | |
| | | | |
| | • | | |
| | | • | |
| | • | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| 3. I hereby certify that the information above is | true and complete to the beat of | my knowledge and ballat | |
| 121112 | A. | | |
| W / / / / / / / / / / / / / / / / / / / | O, nivi | cion Dwill: | 1 20 1006 |
| | TITLE UIVI | sion Drilling Manage | er pare 1-20-1986 |
| Add to the Twee | | | · |
| PROVED BY ON A SPECIAL COMMENT | ran e ar e | | DATE - JAN 2 9 1986 |
| CHOITIONS OF ADDROUGH | 11166 | | DATE - TITE OF TOUT |