

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-11915
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-228
7. Lease Name or Unit Agreement Name SOUTH JUSTIS UNIT "F"
8. Well No. 29
9. Pool name or Wildcat JUSTIS BLY TUBB DRKD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator ARCO Permian	
3. Address of Operator P.O. Box 1710, Hobbs, New Mexico 88240	
4. Well Location Unit Letter <u>K</u> <u>1980</u> Feet From The <u>S</u> Line and <u>1980</u> Feet From The <u>W</u> Line Section <u>36</u> Township <u>25S</u> Range <u>37E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3026' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: SET CIBP ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 5830 CIBP: 5750' PERFS: 5547-5750'

03/13/97: POH W/RODS & TBG. WIH W/BIT, SCRAPER, SUB, AND WORKSTRING TO 5790', POH. WIH & SET ALPHA CIBP @ 5750'. POH, PMP 100 BBLS DOWN CSG TO KILLWELL W/10# BRING. WIH W/2-3/8" TBG. SET @ 5629.27'. LOADED TBG TO 5000#, HELD OK.

~~03/13/97: POH W/RODS & TBG. WIH W/BIT, SCRAPER, SUB, AND WORKSTRING TO 5790', POH. WIH & SET ALPHA CIBP @ 5750'. POH, PMP 100 BBLS DOWN CSG TO KILLWELL W/10# BRING. WIH W/2-3/8" TBG. SET @ 5629.27'. LOADED TBG TO 5000#, HELD OK.~~

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murkish TITLE Admin Asst DATE 4-28-97  
TYPE OR PRINT NAME KELLIE D MURKISH TELEPHONE NO. 394-1649

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: