Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT | P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088 WELL API NO. 30-025-1224 12224

5. Indicate Type of Lease
STATE

6. State Oil & Gas Lease No.

FEE 🔀

		1/2010
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name United Royalty "A" #3
I. Type of Well: OIL XX GAS WELL XX WELL OTHER		West Dollarhide Drinkard #5
2. Name of Operator		0 11/11 1/
Texaco Exploration & Production, Inc.		8. Well No. 3, 5
3. Address of Operator		9. Pool name or Wildcat
P. O. Box 3109, Midland, TX 79702	Dollarhide:	Queon 'Wollarhide; Juby-
4. Well Location Unit Letter _F :2310 Feet From TheNorth		10 Feet From The West Line
		NMPM Lea County
10. Elevation (Show whether	r DF, RKB, RT, GR, etc.)	
		
11. Check Appropriate Box to Indicate	Nature of Notice, Re	eport, or Other Data
NOTICE OF INTENTION TO: SUBS		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON XX	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CE	
OTHER:	OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103. UNITED ROYALTY "A" #3 IS Y SIDE, WEST DOLL		
1) Notify Oil Conservation Division 24 housr 2) MIRU, nipple up BOP, POH with 2-1/16 tubi	before move-in	
3) NU on Z side, test tubing, squeeze 40 sx 4) String out of model "D" packer, circulate	. hole with 9.8 m	essure test ud @ 6530
3) Spot 20 sx cement from 5340 to 5240 (Glor	ieta)	
6) Spot 20 sx cement from 4130 to 4030 (San	Andres)	
7) Spot 40 sx cement from 3820 to 3420 (Quee	n)	
8) Spot 20 sx cement from 2770 to 2670 (Yate	s)	
9) Spot 20 sx cement from 2620 to 2520 (B Sa	1t)	
10) Spot 40 sx cement from 1390 to 1190 (TSAL	T & ANHY)	
11) Spot 10 sx cement from 30 to surface		
12) Cut off wellhead, install dry hole marker		
I hereby certify that the information above is true and complete to the best of my knowledge and	t beiref.	
2// · / m / .//	The Ketroleum	Ensiner 9/23/97
SKINATURE Marid Wi bleam	TIP Known	Inserver 1/23/9/

1 WH 1 MV3

TYPE OR PRINT NAME

(Thus space for State Use)

AFTROVED BY-

DATE -