

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-9519

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- Water injection well
Name of Operator Sirgo-Collier, Inc.		
Address of Operator P. O. Box 3531, Midland, Texas 79702		
Location of Well UNIT LETTER <u>M</u> <u>618</u> FEET FROM THE <u>South</u> LINE AND <u>618</u> FEET FROM <u>West</u> THE <u>South</u> LINE, SECTION <u>29</u> TOWNSHIP <u>24S</u> RANGE <u>38E</u> NMPM.		

7. Unit Agreement Name West Dollarhide Queen Sand Unit
8. Farm or Lease Name
9. Well No. 17
10. Field and Pool, or Wildcat Dollarhide Queen
12. County Lea

15. Elevation (Show whether DF, RT, GR, etc.) 3171' GR
---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-16-88 Set cement retainer @ 2667'. Pump 110 sx with 5 sx on top of retainer.

2-17-88 Perf 5-1/2" casing @ 1250'. Set cement retainer @ 1150'. Pump 45 sx with 5 sx on top of retainer. Perf 5-1/2" casing @ 499'. Pump 25 sx with 5 sx on top of retainer. Set tubing @ 60', circ hole to surface with 15 sx. Cut wellhead off and install P&A marker. Rig down. (Carr Well Service)

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Amy L. Whitley TITLE Agent DATE February 29, 1988

APPROVED BY R. D. [Signature] TITLE OIL & GAS INSPECTOR DATE MAR 22 1988

CONDITIONS OF APPROVAL, IF ANY:

E

RECORDED  
MAR 2 - 1988  
OCD  
HOBBS OFFICE