NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Natur	e of Report by Checking Bel	ow	
REPORT ON BEGINNING DRILLING OPERATIONS		ON RESULT OF TEST	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	X REPORT O OPERATIO	ON RECOMPLETION ON	REPORT ON (Other)	
		September 5, 1957	Midland	, Texas
	•	(Date)		(Place)
Following is a report on the work	done and the results	obtained under the heading n	oted above at the	
J.P. Gibbins			Fowler Hair	
Hobbs Pipe & Supply (Co.	, Well No4	(Lease) NW in the	7 30 30 30
Contractor T, R, NMPM., Do.	')			
The Dates of this work were as folows:	Sept. 27, 28,	29, 30 Oct. 1, 1950)	
		July	7 1 6	, _o 56
Notice of intention to do the work (was) (Alaman) submitted	on Form C-102 on	(Cross out incorrect words)	, 1 <i>J</i>
and approval of the proposed plan (was) (obtained.			
DETAI	LED ACCOUNT OF	WORK DONE AND RESU	LTS OBTAINED	
Circulate hole				
Spot 25 sks cem Pull tubing. Shot casing @ 2 Pull casing. Run tubing spot Spot 25 sks. pl Spot 25sks @ 30	030'. cement plug @ ug @ 1185'. 0'.		•	
Spot 25 sks cem Pull tubing. Shot casing @ 2 Pull casing. Run tubing spot Spot 25 sks. pl Spot 25sks @ 30	030'. cement plug @ ug @ 1185'. 0'.	20301.		g. Supt.
Spot 25 sks cem Pull tubing. Shot casing @ 2 Pull casing. Run tubing spot Spot 25 sks. pl Spot 25sks @ 30 Install 4" mark	ogo'. cement plug e ug @ 1185'. o'. er in top plug	J.P. Gibbins	Orl	e)
Spot 25 sks cem Pull tubing. Shot casing @ 2 Pull casing. Run tubing spot Spot 25 sks. pl Spot 25 sks. pl Spot 25 sks. pl Install 4" mark Witnessed by G.E. McDanf's I'e)	ogo'. cement plug e ug @ 1185'. o'. er in top plug	J.P. Gibbins (Company) I hereby certify the to the best of my Name	Drl. (Title at the information given abore knowledge.	e)
Spot 25 sks cem Pull tubing. Shot casing @ 2 Pull casing. Run tubing spot Spot 25 sks. pl Spot 25 sks. pl Spot 25 sks. pl Spot 25 sks. pl Approved: Witnessed by G.E. McDanf's I'e)	ogo'. cement plug e ug @ 1185'. o'. er in top plug	J.P. Gibbins (Company) I hereby certify the to the best of my	Drl. (Title at the information given abore knowledge.	e)
Spot 25 sks cem Pull tubing. Shot casing @ 2 Pull casing. Run tubing spot Spot 25 sks. pl Spot 25 sks. pl Spot 25 sks. pl Spot 25 sks. pl Approved: OIL CONSERVATION OIL CONSERVATION	ogo'. cement plug e ug @ 1185'. o'. er in top plug	J.P. Gibbins (Company) I hereby certify the to the best of my Name Position Representing	Drl. (Title at the information given abore knowledge.	e) ove is true and complet