NEW XICO OIL CONSERVATION COMM ION

SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

						
NOTICE OF INTENTION TO TEST CASING SHUT-OFF			NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL			
NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO REPAIR WELL			NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING NOTICE OF INTENTION TO PLUG WELL			X
NOTICE OF INTENTION	N TO DEEPEN WELL					
	Box 1032,	Midland	l, Texas	July 16,	1956	
			Place		Date	
OIL CONSERVATION CO Santa Fe, New Mexico	OMMISSION,					
Gentlemen:				J. P. Gibbi	ins	
Following is a notice of i	intention to de certain t	work as descri	bed below at the	Well No.	MM \$	NW
	24s _{r.} 38e			VV CII 110		
T.FA			М. Р. М.,	NAMED OF STREET		Field.
DOM	Cou	•				
	FULL DETAILS	OF PROP	OSED PLAN O	F WORK		
FOLLOW	INSTRUCTIONS IN TH	IE RULES AT	ID REGULATION	S OF THE COMMI	.551011	
Move in cas Spot 25 sac	Remove pumpin ing pullers. ks cement on p	Load holerforati	e with 9 1 ons (3724-	b. mud. 3706).		
Move in cas Spot 25 sac Pull tubing Spot 25 sac	ing pullers. ks cement on p . Cut 52" Cas ks cement at t	Load holerforations @ 22	e with 9 1 ons (3724- 50. Pull	b. mud. 3706). casing.		
Move in cas Spot 25 sac Pull tubing Spot 25 sac Set 4" Pipe Move pipe p	ing pullers. ks cement on p . Cut 52" Cas ks cement at t Marker. ullers off.	Load holerforations @ 22	e with 9 1 ons (3724- 50. Pull	b. mud. 3706). casing.		
Move in cas Spot 25 sac Pull tubing Spot 25 sac Set 4" Pipe	ing pullers. ks cement on p . Cut 52" Cas ks cement at t Marker. ullers off.	Load holerforations @ 22	e with 9 1 ons (3724- 50. Pull	b. mud. 3706). casing.		
Move in cas Spot 25 sac Pull tubing Spot 25 sac Set 4" Pipe Move pipe p Clean up lo The following 2:30 P.M. 7/23 25 SX plu 25 sx plu	ing pullers. ks cement on p cut 52" Cas ks cement at t Marker. ullers off. cation. changes were mad 3/56: ug at top of Salt ug at base of sur	Load hollerforations @ 22 op of 8-	e with 9 1 ons (3724- 50'. Pull 5/8" Casin	b. mud. 3706). casing.	Mr. MeDan	iel
Move in cas Spot 25 sac Pull tubing Spot 25 sac Set 4" Pipe Move pipe p Clean up lo The following 2:30 P.M. 7/23 25 SX plu 25 sx plu 5 to 10 s	ing pullers. ks cement on p . Cut 52" Cas ks cement at t Marker. ullers off. cation. changes were mad 3/56: ug at top of Salt	Load hollerforations @ 22 op of 8-	e with 9 1 ons (3724- 50'. Pull 5/8" Casin	b. mud. 3706). casing. S-	Mr. MeDan	iel
Move in cas Spot 25 sac Pull tubing Spot 25 sac Set 4" Pipe Move pipe p Clean up lo The following 2:30 P.M. 7/2 25 SX plu 25 sx plu 5 to 10 s	ing pullers. ks cement on p cut 52" Cas ks cement at t Marker. ullers off. cation. changes were mad 3/56: ug at top of Salt ug at base of sur	Load hollerforations @ 22 op of 8-	e with 9 1 ons (3724- 50'. Pull 5/8" Casin	b. mud. 3706). casing.		lel
Move in cas Spot 25 sac Pull tubing Spot 25 sac Set 4" Pipe Move pipe p Clean up lo The following 2:30 P.M. 7/2 25 SX plu 25 sx plu 5 to 10 s	ing pullers. ks cement on p cut 52" Cas ks cement at t Marker. ullers off. cation. changes were mad 3/56: ug at top of Salt ug at base of sur	Load hollerforations @ 22 op of 8-	e with 9 1 ons (3724- 50'. Pull 5/8" Casin	b. mud. 3706). casing. eversation with		iel
Move in cas Spot 25 sac Pull tubing Spot 25 sac Set 4" Pipe Move pipe p Clean up lo The following 2:30 P.M. 7/2 25 SX plu 25 sx plu 5 to 10 s	ing pullers. ks cement on p cut 52" Cas ks cement at t Marker. ullers off. cation. changes were mad 3/56: ug at top of Salt ug at base of sur	Load hollerforations @ 22 op of 8-	se with 9 1 ons (3724-250. Pull 5/8" Casing telephone con	b. mud. 3706). casing. eversation with	operator weel	iel
Move in cas Spot 25 sac Pull tubing Spot 25 sac Set 4" Pipe Move pipe po Clean up loo The following 2:30 P.M. 7/25 25 SX plu 25 sx plu	ing pullers. ks cement on p cut 52" Cas ks cement at t Marker. ullers off. cation. changes were mad 3/56: ug at top of Salt ug at base of sur	Load hollerforations @ 22 op of 8-	J. P. By Position Dri Sen	dibbins Company or of the communications reduced to the computation of the computation reduced to the communications reduced to the computation reduced to the computation reduced to the communications reduced to the communication reduced to the com	operator Lintendent	
Move in cas Spot 25 sac Pull tubing Spot 25 sac Set 4" Pipe Move pipe p Clean up lo The following 2:30 P.M. 7/2 25 SX plu 25 sx plu 5 to 10 s Approved except at follows:	ing pullers. ks cement on p cut 52" Cas ks cement at t Marker. ullers off. cation. changes were mad 3/56: ug at top of Salt ug at base of sur	Load holerforations @ 22 op of 8- de as per de se pipe marker	J. P. By Position Dri Sen	Gibbins Company or of the company of t	operator Lintendent	***************************************
Move in cas Spot 25 sac Pull tubing Spot 25 sac Set 4" Pipe Move pipe p Clean up lo The following 2:30 P.M. 7/2 25 SX plu 25 sx plu 5 to 10 s	ing pullers. ks cement on p cut 52" Cas ks cement at t Marker. ullers off. cation. changes were mad 3/56: ug at top of Salt ug at base of sur ex top plug with	Load holerforations @ 22 op of 8- de as per de se pipe marker	J. P. By Position Dri Sen Name J. P	dibbins Company or of the communications reduced to the computation of the computation reduced to the communications reduced to the computation reduced to the computation reduced to the communications reduced to the communication reduced to the com	intendent	