	Roswell, NM 88201 1 - Forem	Ging8240 Laura Richardson-Midlan an 1 - File
	Form 9–331 .	Form Approved.
	Dec. 1973 UNITED STATES	Budget Bureau No. 42-R142
	DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	NM-0349952
		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME West Dollarhide Drinkar
	(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
	1. oil gas well well well other	West Dollarhide Drinkar 9. WELL NO.
	2. NAME OF OPERATOR	15
	Getty Oil Company	10. FIELD OR WILDCAT NAME Dollarhide Tubb-Drinkar
-	3. ADDRESS OF OPERATOR P.O. Box 730 Hobbs, NM 88240	11. SEC., T., R., M., OR BLK. AND SURVEY C
	4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 30, T24S, R38E
	below.) AT SURFACE: Unit ltr. A 990' FNL & 990' FEL	12. COUNTY OR PARISH 13. STATE
	AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Lea NM 14. API NO.
	16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
		15. ELEVATIONS (SHOW DF, KDB, AND W 3196' DF
	REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5130 DI
	TEST WATER SHUT-OFF	
	SHOOT OR ACIDIZE	
	REPAIR WELL XX L	(NOTE: Report results of multiple completion or zo change on Form 9–330.)
	MULTIPLE COMPLETE	
	ABANDON*	
	(other)	
	17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta	directionally drilled, give subsurface locations a
	including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	ent to this work.)*
	measured and true vertical depths for all markers and zones pertine	ent to this work.)*
	measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to <u>+</u> 3	3100'.
	 measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to ± 3 3. Cement liner in hole and drill out. 4. Selectively perforate Drinkard 6623' 	3100'.
	 measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to + 3 3. Cement liner in hole and drill out. 4. Selectively perforate Drinkard 6623'- 5. Acidize with + 7,500 gals. 15% Hcl. 	3100'.
	 measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to ± 3 3. Cement liner in hole and drill out. 4. Selectively perforate Drinkard 6623' 	-6698' 2 SPF.
	 measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to + 3 3. Cement liner in hole and drill out. 4. Selectively perforate Drinkard 6623'- 5. Acidize with + 7,500 gals. 15% Hcl. 	-6698' 2 SPF.
	 measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to + 3 3. Cement liner in hole and drill out. 4. Selectively perforate Drinkard 6623'- 5. Acidize with + 7,500 gals. 15% Hcl. 	-6698' 2 SPF.
	 measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to + 3 3. Cement liner in hole and drill out. 4. Selectively perforate Drinkard 6623'- 5. Acidize with + 7,500 gals. 15% Hcl. 	-6698' 2 SPF.
	 measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to + 3 3. Cement liner in hole and drill out. 4. Selectively perforate Drinkard 6623'- 5. Acidize with + 7,500 gals. 15% Hcl. 	Baloo'. -6698' 2 SPF. JUL 21 Boswell,
	 measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to <u>+</u> 3. Cement liner in hole and drill out. 4. Selectively perforate Drinkard 6623'- 5. Acidize with <u>+</u> 7,500 gals. 15% Hcl. 6. Place well on production. 	Baloo'. -6698' 2 SPF. JUL 21 Boswell,
	 measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to <u>+</u> 3. Cement liner in hole and drill out. 4. Selectively perforate Drinkard 6623' 5. Acidize with <u>+</u> 7,500 gals. 15% Hcl. 6. Place well on production. Subsurface Safety Valve: Manu. and Type	siloo'. -6698' 2 SPF. JUL 21 Poswell, 1 Set @
Ş	<pre>measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to <u>+</u> 3. Cement liner in hole and drill out. 4. Selectively perforate Drinkard 6623'- 5. Acidize with <u>+</u> 7,500 gals. 15% Hcl. 6. Place well on production. Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct SIGNED</pre>	siloo'. -6698' 2 SPF. JUL 21 Boswell, Set @ tendentale July 19, 1983
, L	<pre>measured and true vertical depths for all markers and zones pertine 1. Rig up pulling unit. 2. Run 4" flush joint liner 6698' to + 3. Cement liner in hole and drill out. 4. Selectively perforate Drinkard 6623'. 5. Acidize with + 7,500 gals. 15% Hcl. 6. Place well on production. Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct SIGNED Dale R. proceeding the space for Federal or State of (Orig. Sed.) From W. Christien.</pre>	ent to this work.)* 3100'. -6698' 2 SPF.
Ļ	measured and true vertical depths for all markers and zones pertine Rig up pulling unit. Run 4" flush joint liner 6698' to + 1 Cement liner in hole and drill out. Selectively perforate Drinkard 6623'. Acidize with + 7,500 gals. 15% Hcl. Place well on production. Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED Date R. CORCUMENTAL True Area Superint (This space for Federal or State of the space for Feder	siloo'. -6698' 2 SPF. JUL 21 Boswell, Set @ tendentale July 19, 1983