Form 9-331 Dec. 1973

1-R. J. STARRAK-TULSA 1-A. B. CARY-MID D

1-BB, OFC TECH

COPY TO O. C.

irm Approved. Judget Bureau No. 42-R1424

1-ELB, ENGR.

UNITED STATES

DEPARTMENT OF THE INTERIOR

٠.	LEASE • I.C = 069052	MM10186
6		OTTES OF TOIRS MANAGE

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT N	AME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAM	E
1. oil gas well other	West Dollarhide 9. WELL NO.	Drinkard Unit
2. NAME OF OPERATOR	_50_	•
Cetty Oil Company	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Dollarhide Tubb-Drinkard	
P. O. Box 730, Hobbs, NM 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA	
below.)	Sec. 31, T-24S,	
AT SURFACE: Unit ltr. G, 2130' FNL & 1650' FEL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH	
AT TOTAL DEPTH:	Lea	NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.	, '
REPORT, OR OTHER DATA	1F CLEVATIONS (SALE)	
, <u>,</u>	15. ELEVATIONS (SHOW 3135' DF	DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	2122 Dt	
TEST WATER SHUT-OFF		•
FRACTURE TREAT		
SHOOT OR ACIDIZE REPAIR WELL	4	
PULL OR ALTER CASING	(NOTE: Report results of mu change on Form 9-3	
MULTIPLE COMPLETE		
CHANGE ZONES		
ABANDON* [] [] (other) Clean out and run liner		
(other) Crean out and run Tiner		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen	rectionally drilled give sub-	give pertinent dates, surface locations and
1. Rig up pulling unit.		
2. Pull rods and pump.		
3. Clean out to TD.	¬ □ 0 €	r na E la
4. Run 5" 13# liner from TD-+ 5800'.		
5. Cement liner.		
6. WOC 24 hrs.	1AN 2	9 1980
7. Drill out to top of liner.		
8. Test liner top to 1000 psi.	U. S. GFOLOO	MCAL SURVEY
9. Clean out inside liner to float collar.	HOBBS, NE	W MEXICO
10. Selectively perforate the lower Drinkard.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
11. Acidize perforations.		
12. Run tbg., pump, and rods.		
subsurface Safety valve: Manu. and Type tion.	Set (@ Ft.
18. I hereby certify that the foregoing is true and correct		. · · · · · · · · · · · · · · · · · · ·
signed Dale R. Crockett Area Supt.	DATE1-18-8	0
(This space for Federal or State office	ce use)	· · · · · · · · · · · · · · · · · · ·
APPROVED BY TITLE	DATE	-
CONDITIONS OF APPROVAL, IF ANK		