

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-12291
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No. 010926
7. Lease Name or Unit Agreement Name West Dollarhide Drinkard Unit
8. Well No. 65
9. Pool name or Wildcat West Dollarhide

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER Water Injection
2. Name of Operator Texaco E&P, Inc.
3. Address of Operator P. O. Box 3109 Midland, TX. 79702
4. Well Location Unit Letter J : 2090 Feet From The FSL Line and 1650 Feet From The FFL Line Section 31 Township T245 Range 38E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) DF 8" 3117' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☒	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- EST. injection rate down tub. Injection PRKER @ 6028'
- SQ thru Paker. w/150SK Class C-WOC R.I. WL & cut tub @ 6000 (Tubbs & Drinkard perf. 6012-6317)
- Spot plug 20SK (5800'-6000') WOC & Tag.
- Circ csq w/25# per bbl. Salt gel & brine to surface.
- POOH to 3850' Spot 25 SKS Class C from 3850' - 3700' & WOC & Tag. (Queens)
- POOH to 2900' Spot 25 SKS Class C from 2900' - 2750' WOC & Tag.
- POOH to 1350' Spot 25 SKS Class C from 1350' - 1200' WOC & Tag.
- POOH to 350' Spot 50 SKS Class C from 350' - Surface.
- Cut off wellhead & weld cap & install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. J. Harding III TITLE Engineer DATE 6/15/94
TYPE OR PRINT NAME R. J. Harding III TELEPHONE NO. 915 686-4816

(THIS SPACE FOR SIGNATURE)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JUN 20 1994