DISTRIBUTION			Form C-103 Supersedes Old C-102 and C-103
ITA FE	NEW	MEXICO OIL CONSERVATION COMMIS	C-102 and C-103 SSION Effective 1-1-65
.Ε			
.G.S.			5a. Indicate Type of Lease
ND OFFICE			State XX Fee
ERATOR			5, State Cil & Gas Lease No.
			В-9311
DO NOT USE THIS FORM USE "AF	UNDRY NOTICES AL	ND REPORTS ON WELLS OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RE (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL WELL	OTHER.		7. Unit Agreement Name West Dollarhide Queen Sand Uni
Skelly 011 Company	7		8. Farm or Lease Name  West Dollarhide Queen Sand Uni
Address of Operator P. O. Box 1351, Mi		9701	9. Well No. 45
4Location of Well UNIT LETTER M	330	South 330	10. Field and Pool, or Wildcat  Dollarhide Queen
T.To. o.t.	, <u> </u>	TOWNSHIP 24S RANGE 38E	NMPM.
mmmmm		evation (Show whether DF, RT, GR, etc.)	12. County
	11111111111111111111111111111111111111	3133' DF	Lea Lea
	A A Tarana i A A B		
	OF INTENTION TO	Sox To Indicate Nature of Notice,	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	P	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	•	COMMENCE DRILLING	
<u> </u>	c	HANGE PLANS CASING TEST AND CEN	
PILL OR ALTER CASING			AENT JQB
PULL OR ALTER CASING		OTHER	ENT JQB
OTHER PERFORATE, 8		OTHER	BDL TNAN
OTHER Perforate, 8	acidize and test	t upper X	t dates, including estimated date of starting any proposed
Perforate, a  Penrose Zone 17. Describe Proposed or Compl work) SEE RULE 1103.  1) Rig up workove 2) Set 7" bridge 3) Spot 500 gals 4) Perforate 7" ( 3580-3588', 3: 5) Set packer and Pull packer. 6) If gas product	er rig. Pull replug at 3630', 7-1/2% acid. DD casing with 2599-3615', 3619-11 treat perfs. The street run tubing the street run tubing acid.	state all pertinent details, and give pertinent ods and tubing. plugging off open-hole second shots per foot as follows -3620' and 3622-3625'. with 1500 gals. 15% acid in	t dates, including estimated date of starting any proposed etion 3650-3772'.  3: 3556-3566', 3572-3578',  3: 3 stages. Swab and test.  Flow. If oil productive and
Perforate, a  Penrose Zone  17. Describe Proposed or Compl  work) SEE RULE 1103.  1) Rig up workove  2) Set 7" bridge  3) Spot 500 gals  4) Perforate 7" (  3580-3588', 3!  5) Set packer and  Pull packer.  6) If gas product  requires being	eted Operations (Clearly er rig. Pull re plug at 3630', 7-1/2% acid. OD casing with 2599-3615', 3619- it reat perfs. with the pumped, run to the pumped, run to the pumped, run to the pumped of the p	state all pertinent details, and give pertinent ods and tubing. plugging off open-hole sectors are follows—3620' and 3622—3625'. with 1500 gals. 15% acid in g and packer and equip to fubing and rods and place be a complete to the best of my knowledge and be a complete to the best of my knowledge.	etion 3650-3772'.  3: 3556-3566', 3572-3578',  3: 3 stages. Swab and test.  Flow. If oil productive and ack on producing status.
Perforate, a  Penrose Zone  17. Describe Proposed or Compl  work) SEE RULE 1103.  1) Rig up workove  2) Set 7" bridge  3) Spot 500 gals  4) Perforate 7" (  3580-3588', 3!  5) Set packer and  Pull packer.  6) If gas product  requires being	eted Operations (Clearly er rig. Pull re plug at 3630', 7-1/2% acid. OD casing with 2599-3615', 3619- it reat perfs. with the pumped, run to the pumped, run to the pumped, run to the pumped of the p	state all pertinent details, and give pertinent ods and tubing. plugging off open-hole sectors are follows—3620' and 3622—3625'. with 1500 gals. 15% acid in g and packer and equip to fubing and rods and place be a complete to the best of my knowledge and be a complete to the best of my knowledge.	t dates, including estimated date of starting any proposed etion 3650-3772'.  3: 3556-3566', 3572-3578',  3: 3 stages. Swab and test.  Slow. If oil productive and ack on producing status.
Perforate, a  Penrose Zone  17. Describe Proposed or Compl  work) SEE RULE 1103.  1) Rig up workove  2) Set 7" bridge  3) Spot 500 gals  4) Perforate 7" (  3580-3588', 3!  5) Set packer and  Pull packer.  6) If gas product  requires being	er rig. Pull replug at 3630', 7-1/2% acid. DD casing with 599-3615', 3619-it treat perfs. with the pumped, run to a pumped, run to a pumped, run to a pumped.	state all pertinent details, and give pertinent ods and tubing.  plugging off open-hole sectors are follows—3620' and 3622—3625'.  with 1500 gals. 15% acid in g and packer and equip to fubing and rods and place be	etion 3650-3772'.  3: 3556-3566', 3572-3578',  3: 3 stages. Swab and test.  Flow. If oil productive and ack on producing status.