

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY  
WASHINGTON, D. C.

SUBMIT IN TRIP DATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032592 - (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NONE

7. UNIT AGREEMENT NAME

NONE

8. FARM OR LEASE NAME

C. C. Fristoe "a" NCT-2

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

Justis-Tubb-Drinkard

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 3, T-25-S, R-37-E

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P. O. Box 728 - Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

This well is located 330' from the East Line, and 330' from  
the North Line of Section 3, T-25-S, R-37-E, Lea County, N. M.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

3184' (D. F.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☒  
☐

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

☐  
☐  
☐  
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

☐  
☐  
☐

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

We propose to do the following work on subject well:

1. Pull the pump equipment.
2. Perforate the Justis-Tubb-Drinkard zone with two jet shots at 6017',  
6022', 6035', 6057', and 6062'.
3. Acidize the old and new perforations with 3000 gals 15% NE acid with  
ball sealers. Swab well, recover load, Shut well In, work on the  
Blinebry Zone.
4. After work has been completed on the Blinebry zone, Test the Justis-  
Tubb-Drinkard zone, and place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

J. G. Elevins, Jr.

TITLE

Assistant District  
Superintendent

DATE

July 28, 1966

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED  
JUL 28 1966

DISTRICT ENGINEER

\*See Instructions on Reverse Side