May 1963)	UNIT' STATES	SUBMIT IN TRIPLICA	Berin approved. C. C. Budget Burean No. 42-B14 5. LEASE DESIGNATION AND SERIALS
ULPA	RTMENT JF THE IN	TERIOR verse side)	<u>ି କ୍ରିଲି କ</u> ୁହାର କାଳ
	GEOLOGICAL SURV		LC-032592-(b)
SUNDRY N	NOTICES AND REPO	rts on wells	
(Do not use this form for	proposals to drill or to deepen of	r plug back to a different reservoir. r such proposals.)	
		AFREN	7. UNIT AGREEN ENT NAME
OIL GAS	HER		
NAME OF OPERATOR			8. FARM OR LEAST NAME
TEXACO Inc.			9. WELL NO. 4 5 - C.C.
ADDRESS OF OPERATOR			9. WELL NO. 7 BOIL DURING LINE
P.O. Box 728,	Hobbs, New Mexico	88240; State requirements.*	10. FIELD AND POOL, OF WEDEAT
	ation clearly and in accordance v	HCBBS, Nate and DD	Justis' Blinebry
At surface	wth Line and 1979	from the East Line of	11. SEC., T., B., ME, OR BEE. AND
$\frac{1980}{\text{From the NO}}$	S, R-37-E, Unit Let	ter F	Sec. 35 T-24 S . R-3
Section 00, 12,			·
14. PERMIT NO.	15. ELEVATIONS (Show w	hether DF, RT, GR, etc.)	12. COUNTY. OR PARISH 137 FTATE
Regular	3184' DF		
16. Che	ck Appropriate Box To Ind	icate Nature of Notice, Report, c	or Other Data Hange State
	F INTENTION TO:	SUB	SEQUENT REPORT OF
[]	E E	WATER SHUT-OFF	HEPATEING WALL
TEST WATER SHUT-OFF	PULL OR ALTER CASING	FRACTURE TREATMENT	ALTERING CABING
FRACTURE TREAT	ABANDON*	SHOOTING OR ACIDIZING	EABANDON MUNT
REPAIR WELL	CHANGE PLANS	(Other)	sults of multiple completion on Well
(Oth)		Completion or Rec	ates, including estimated date of starfun ertical depths for all markers and rouge
		ng work on subject well	
 Perforate down 86, 87, 92, 94 46, and 48'. Frac down 2-1/2 Mark II Adomite Pump 200 gal stage add un 	2-7/8" casing w/1 ,97, 5106, 10, 29, 3 16" tubing w/25,000 e and 1 ppg 20-40 O 1. NE Acid ahead of	JSPI @5048, 50, 52, 54, 32, 34, 58, 64, 65, 70, gal oil base Poly Frac ttowa Sand in 5 equal st	57, 60, 65, 66, 71, 72, 72, 99, 5200, 29, 30, 32 containing 25 1b/1000 ga
 Perforate down 86, 87, 92, 94 46, and 48'. Frac down 2-1/. Mark II Adomite Pump 200 gai stage add un Swab and place 	2-7/8" casing w/1 97, 5106, 10, 29, 3 16" tubing w/25,000 e and 1 ppg 20-40 O 1. NE Acid ahead of nibeads. on production.	Assistant District	57, 60, 71, 30, while a the set of the set o
 Perforate down 86, 87, 92, 94 46, and 48'. Frac down 2-1/. Mark II Adomite Pump 200 gal stage add un 3. Swab and place Swab and place Swab and place Signed Addition of the space for Federal or the space for Federal or the space of the spac	2-7/8" casing w/1 97, 5106, 10, 29, 3 16" tubing w/25,000 e and 1 ppg 20-40 O 1. NE Acid ahead of nibeads. on production.	Assistant District	57, 60, 71, 30, while a the set of the set o