UNITED STATES (May 1963) DEPARTMENT OF THE INTERI GEOLOGICAL SURVEY		SUBMIT IN TRIPLICALE (Other instructions on r verse side)	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. LC-032592 (a)		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
OIL GAS WELL OTHER		医印尼耳氏中间	7. UNIT AGREEMENT NAM:		
2. NAME OF OPERATOR TEXACO I	1C.	JAN 9 1978	8. FARM OR LEASE NAME C. C. Fristoe A		
3. ADDRESS OF OPERATOR P. O. BO	k 728, Hobbs, New Mexico	S CEOLOGICAL SURVE	9. WELL NO.	······································	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990° FSL & 402° FEL of Section 3, T-25-S, R-37-E,			10. FIELD AND POOL, OR WILDCAT Justis Blinebry		
Unit let	er 'P', Lea County, Nev	, T-25-5, R-37-E, Mexico	11. SEC., T., R., M., OR BLE SURVEY OR AREA	C. AND	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT,	an eta)	Sec. 3, T-25-S,		
Regular	3147 (DF)	gr, etc.)	Lea Lea	New Mexico	
16. Check A	Appropriate Box To Indicate Natur	re of Notice, Report, or	Other Data	***************************************	
NOTICE OF INTENTION TO:			QUENT REPORT OF:	UENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WE	LL	
FRACTURE TREAT SHOOT OR ACIDIZE	MULTIPLE COMPLETE ABANDON*	FRACTURE TREATMENT	ALTERING CASI		
REPAIR WELL	CHANGE PLANS	SHOOTING OR ACIDIZING (Other)	ABANDONMENT		
	ak & Addl. Perf.	Completion or Recom	ts of multiple completion on pletion Report and Log form	.)	
17. DESCRIBE PROPOSED OR COMPLETED O proposed work. If well is direct nent to this work.) *	PERATIONS (Clearly state all pertinent det tionally drilled, give subsurface locations	ails, and give pertinent date and measured and true verti	s, including estimated date of cal depths for all markers a	of starting any nd zones perti-	
3. Locate csg leak & s 4. Perforate 2 7/8" OI 5. Acidize perforation 6. Perforate 2 7/8" OI	OD csg @ 6075' & dump 35 queeze. DOC & test. csg w/2-JSPF @ 5782', 8 s 5782' - 5819' w/1500 g csg w/2-JSPF @ 5596', 5 s 5596' - 5673' w/750 gs swab.	36', 5804', 09', 1 gal 15% NE Acid us 661', & 5673'.	.4', & 5819'. sing 10 ball seal Set RBP @ 5700'.	ers.	
18. I hereby certify that the foregoing	Jan Prince Control of the Control of				
SIGNED	TITLE Asst.	Dist. Superinten	dent DATE 1-5-	78	
(This space for Federal or Stude office use)			APPROVED		
APPROVED BY CONDITIONS OF APPROVAL, IF	ANY:		JAN 9 19	78	

JANA O INTE

CLU White R. C.

OF VENERAL A

of the country of the country