

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-55

5a. Indicate Type of Lease

State ☐

Fed. ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator UNION TEXAS PETROLEUM CORPORATION
3. Address of Operator 1300 Wilco Building, Midland, Texas 79701
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>25-S</u> RANGE <u>37-E</u> NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

Sunray

9. Well No.

1

10. Field and Pool, or Wildcat

Justis Blinebry

15. Elevation (Show whether DF, RT, GR, etc.)

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER Plug Back & Recomplete

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RU & re-enter well. Run 2 7/8" work string w/4 1/2" EZ drill SV retainer and set at an approximate depth of 5250'.
2. Squeeze Blinebry perms. 5288 to 5779' w/200 sx. Class "C" cmt. When squeeze obtained, pulled out of retainer and cap w/35' of cmt.
3. Log well from 3500'-2000'.
4. Perforate Penrose portion of the Queen Zone.
5. Set packer at 3150' and frac. w/15,000 gals. of gel. 2% KCL wtr. and sand tagged w/RA material (Determine zone of treatment).
6. Swab test to evaluate Penrose.
7. Perforate upper Queen Zone.
8. Set RBP @ 3175' and frac Queen w/15,000 gal. of gelled 2% KCL wtr. & sand tagged w/RA material. (Determine zone of treatment).
9. Swab test to evaluate.
10. If well is productive, run tubing rods and pump.
11. Place well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Stanley A. Post

TITLE Gas Measurement Analyst

DATE 7-27-76

Orig. Signed by

Jerry Sexton

Dist. I, Supv.

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

1976 JUL 29 1976