

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> 0 Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>W.S.W.</u>	7. Unit Agreement Name
2. Name of Operator <u>Amerada Hess Corporation</u>	8. Farm or Lease Name <u>L.M.W.U.</u>
3. Address of Operator <u>Box "D" - Monument, New Mexico 88265</u>	9. Well No. <u>7</u>
4. Location of Well UNIT LETTER <u> </u> <u>1530</u> FEET FROM THE <u>South</u> LINE AND <u>135'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>24S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat <u>Langlie Mattix</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3212' DF</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Run 2-3/8" Tbg. to 1592' Pump 500 Sk. cement plug. Load hole and check top of cement. ~~If necessary~~ spot 100 Sk plug in and out of 8-5/8" csg. at 1592'. Spot 100 sk. plug in and out of 10-3/4" csg. at 759'. Spot 10 sk. plug at surface and plug and abandon.

Expire 7/6/77

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H.D. Porter TITLE Admin. Serv. Supv. DATE 7/2/76

APPROVED BY John Runyan TITLE Geologist DATE
CONDITIONS OF APPROVAL, IF ANY: