S comit 3 Copies To Appropriate District Office	State of Ne Energy, Minerals and	Form C-103 Revised March 25, 1999										
District I 1625 N. French Dr., Hobbs, NM 87240 District II 811 South First, Artesia, NM 87210 District III 1000 Rio Brazos Rd. Aztec, NM 87410	OIL CONSERVATION DIVISION 2040 South Pacheco Santa Fe, NM 87505				WELL API NO. <u>30-025-23306</u> 5. Indicate Type of Lease STATE FEE x							
District IV 2040 South Pacheco, Santa Fe, NM 87505						6. State Oil & Gas Lease No.						
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						7. Lease Name or Unit Agreement Name:						
1. Type of Well:     Oil Well     Other Water Injection Well						Langlie Mattix Queen Unit						
2. Name of Operator							8. Well No.					
Gruy Petroleum Management Co.						3						
3. Address of Operator						9. Pool name or Wildcat						
P.O. Box 140907 Irving, Texas 75014-0907						Langlie Mattix 7RV-Qu-Grbq						
4. Well Location Unit LetterM:	feet from the	Sout	:h	line and	890	feet fron	1 the	East	line			
Section 10	Township 25	s R	ange	37E	NMPM		County	Lea				
	10. Elevation (Show wh		R, RKB. 5'КВ	RT, GR, e	etc.)							
11. Check A	ppropriate Box to Indi	icate <sub>1</sub> N	Jature	of Notice	, Report, o	r Other I	Data					
NOTICE OF INTE	ENTION TO:			SU	BSEQUE	NT REP	ORT	OF:				
	PLUG AND ABANDON	F	REMED	IAL WORK			ALTER	ING CASIN	G 🗌			
TEMPORARILY ABANDON	CHANGE PLANS		COMME	NCE DRIL	LING OPNS.			AND DONMENT				
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING CEMEN	TEST AN T JOB	D		, (2) (142					
OTHER:			OTHER:									

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Gruy Petroleum Mangagement Co., respectfully request approval to Temporarily Abandon this inactive injection well as per the attached procedure:

- 1. MIRU well service rig. Release pkr., circulate hole and POH w/tubing.
- 2. RIH with CIBP and set @3350' with 35' cement on top.
- 3. Test CIBP and casing to 500 psi.
- 4. RD and move off well. Leave well as TA'd.

I hereby certify that the information above is		the best of my knowledge and belief.		
SIGNATURE ILON EL	onolge	TITLE Sr. Regulatory Analyst	DATE _	6-25-2002
Type or print name Don Aldridge	4		Telephone No.	469-420-2728
(This space for State use)				
APPROVED BY Conditions of approval, if any:	TTE GARY MILL	A CARESCIATATION AND A CARESCIATA	DAT <b>JUL</b>	<del>2 2002</del>

OC FIELD REPRESENTATION DATE · • •



