

2. TO: LAND OFFICE	
3. DIVISION	
4. COUNTY	
5. FILE	
6. U.S.G.S.	
7. LAND OFFICE	
8. OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-101
Effective 1-1-65

1. SURFACED HOT-TEES AND PULL-OUTS OF WELLS		2. Indicate Type of Lease State ☒ Fee ☐ 3. Section, Range & Township
4. Well No. <u>1751</u> State <u>TX</u> 5. Operator <u>Sun-Tex Co. Inc.</u> 6. P. O. Box <u>8067, Midland, Texas 79704</u> 7. Unit No. <u>1550</u> Direction <u>South</u> Line and <u>1751</u> 8. East <u>12</u> Township <u>25-S</u> Range <u>37-E</u> 9. Depth <u>3103' 63"</u>		10. Name of Lessee <u>S. W. Eaton</u> 11. Name of Operator <u>Justice, Lindberg & Justice, Rob Brinkard</u> 12. Date <u>12-01-80</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INFORMATION FOR: 1. Permanent or Semi-Permanent ☐ 2. Plug and Abandonment ☐ 3. Borehole Work ☐ 4. Altering or Changing ☐ 5. Temporary or Temporary ☐ 6. Change Plans ☐ 7. Commercial Wellbore Work ☐ 8. Plug and Abandonment ☐ 9. Pull on After Casing ☐ 10. Other ☒ 11. Casing Seal and Cement Job ☐ 12. Other ☐	
--	--

13. Describe in detail the work to be done, including all pertinent details, and give pertinent data, including estimated date of starting and proposed work to be completed.
1. RABOTH. Kill well, pull rods and pump. Install DPH. Pull short string.
 2. Reset GSP & pull long string and packer.
 3. Run treating packer on 2 3/8" tbg. Set packer at 5103'.
 4. Acidize perfs 5103'-5174' w/5000 gals. acid.
 5. Pull tbg. and packer.
 6. Run 2 3/8" tbg. with HA, SA, etc.
 7. Run pump and rods, place well on pump, recover load and test.

ILLEGIBLE

14. Primary Party, who is the owner of the well and the operator, must sign this report.

15. Signature R. J. Lindberg Reg. Operations Sign. Date 12-01-80

16. Signature [Signature] Date [Date]

17. Signature [Signature] Date [Date]

18. Signature [Signature] Date [Date]

19. Signature [Signature] Date [Date]

20. Signature [Signature] Date [Date]