

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Langlie-Jal Unit
2. NAME OF OPERATOR UNION TEXAS PETROLEUM CORPORATION		8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR 1300 Wilco Building, Midland, Texas 79701		9. WELL NO. 60
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter "I", 660' FEL & 1830' FSL		10. FIELD AND POOL, OR WILDCAT Langlie-Mattix (Queen)
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3220.1' GL	11. SEC., T., R., M., OR BLK. AND SURVEY OR ABMA Sec. 5; T-25-S; R-37-E
		12. COUNTY OR PARISH 13. STATE Lea New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input checked="" type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. RU and re-enter well.
2. Pump down tubing and spot 100 gallons of iron stabilized 15% acid across pumps.
3. Acidize well with 2000 gallons of iron stabilized 15% acid in four 500 gallon stages.
4. After leaving well shut in 6 to 8 hours, return to production.

18. I hereby certify that the foregoing is true and correct

SIGNED Stanley A. Jant

TITLE Senior Production Analyst

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

4-15-77  
**APPROVED**  
ABR  
BERNARD MOROZ  
DISTRICT ENGINEER

RECEIVED

1977

OIL C. COMM.  
HOBBS, H. M.