Form 3160-5 November 1983) Formeriy 9-331) DEPARTN OF THE INTERIOR (Other instruction of the instruction of	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEARE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTES OR TRIBE NAME
WELL X WELL OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	Langlie-Jal Unit
Union Texas Petroleum Corp. Attn: Ken E. White	S. PARM OR LEASE NAME
P.O. Box 2120 Houston, TX 77252-2120	9. WELL HO.
See also space 17 below.) At surface	76 10. FIELD AND POOL, OR WILDCAY
1980 FNL & 660' FWL, Unit Letter E	Langlie-Mattix (Queer
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	Sec. 9-25S-37E
Check Assessment B. T. L.	
Check Appropriate Box To Indicate Nature of Notice, Report, or Ot	
PULL OB ALTER CASING	FT REPORT OF:
MALTIPLE COMPLETE	REPAIRING WELL
SHOOT OR ACIDIZE ABANDON* SEPARE WELL ABANDON* SHOOTING OR ACIDIZING	ALTERING CARING
(Other)	Temporarily X
/ No.	
Observed the Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, in nent to this work.) 10-28-88	maitinia complete.
10-28-88 1. POH W/Rod & pmp, release tbg anchor & install BOP. 2. POH W/Production string. 3. GIH W/CIBP on production string and set CIBP @ 3400'-10,00 Pressure test casing to 500 psig surface pressure. 5. Reverse circulate one annular plug tbg volume of inhibited POH W/production tbg & make sure hole is loaded w/packer for Remove BOP & install wellhead w/tapped bull plug, needle vogauge adapter. *FLUID SPECIFICATIONS	multiple completion on Well on Report and Log form.) Cluding estimated date of starting any depths for all markers and sense perting the packer fluid. * packer fluid. luid.** alve, a pressure
10-28-88 1. POH W/Rod & pmp, release tbg anchor & install BOP. 2. POH W/Production string. 3. GIH W/CIBP on production string and set CIBP @ 3400'-10,004. Pressure test casing to 500 psig surface pressure. 5. Reverse circulate one annular plug tbg volume of inhibited POH W/production tbg & make sure hole is loaded w/packer for Remove BOP & install wellhead w/tapped bull plug, needle vogauge adapter.	multiple completion on Well on Report and Log form.) Cluding estimated date of starting any depths for all markers and sence porti- * packer fluid. luid.** alve, & pressure
10-28-88 1. POH W/Rod & pmp, release tbg anchor & install BOP. 2. POH W/Production string. 3. GIH W/CIBP on production string and set CIBP @ 3400'-10,00 Pressure test casing to 500 psig surface pressure. 5. Reverse circulate one annular plug tbg volume of inhibited POH W/production tbg & make sure hole is loaded w/packer for Remove BOP & install wellhead w/tapped bull plug, needle vogauge adapter. *FLUID SPECIFICATIONS	multiple completion on Well on Report and Log form.) Cluding estimated date of starting any depths for all markers and sense porti- * packer fluid. luid.** alve, a pressure
10-28-88 1. POH W/Rod & pmp, release tbg anchor & install BOP. 2. POH W/Production string. 3. GIH W/CIBP on production string and set CIBP @ 3400'-10,00 4. Pressure test casing to 500 psig surface pressure. 5. Reverse circulate one annular plug tbg volume of inhibited 6. POH W/production tbg & make sure hole is loaded w/packer f 7. Remove BOP & install wellhead w/tapped bull plug, needle v. gauge adapter. **FLUID SPECIFICATIONS 20 gal of unichem TH-606 per 100 BBL of fresh was all the production to the sure hole is loaded with the foregoing is true and correct before that the foregoing is true and correct BIGNED **HILLE Reg. Permit Coord** **TITLE Reg. Permit Coord** **TITLE Reg. Permit Coord**	multiple completion on Well on Report and Log form.) Cluding estimated date of starting any depths for all markers and sense perting the property of the perting and sense perting and sense perting the perting and sense perting
10-28-88 1. POH W/Rod & pmp, release tbg anchor & install BOP. 2. POH W/Production string. 3. GIH W/CIBP on production string and set CIBP @ 3400'-10,00 4. Pressure test casing to 500 psig surface pressure. 5. Reverse circulate one annular plug tbg volume of inhibited 6. POH W/production tbg & make sure hole is loaded w/packer f 7. Remove BOP & install wellhead w/tapped bull plug, needle v. gauge adapter. **FLUID SPECIFICATIONS 20 gal of unichem TH-606 per 100 BBL of fresh wat a series of the serie	multiple completion on Well on Report and Log form.) Cluding estimated date of starting any depths for all markers and some pertinated date of starting any depths for all markers and some pertinated date. * packer fluid. luid.** alve, @ pressure
10-28-88 1. POH W/Rod & pmp, release tbg anchor & install BOP. 2. POH W/Production string. 3. GIH W/CIBP on production string and set CIBP @ 3400'-10,00 4. Pressure test casing to 500 psig surface pressure. 5. Reverse circulate one annular plug tbg volume of inhibited 6. POH W/production tbg & make sure hole is loaded w/packer f 7. Remove BOP & install wellhead w/tapped bull plug, needle v. gauge adapter. **FLUID SPECIFICATIONS 20 gal of unichem TH-606 per 100 BBL of fresh was all the production to the sure hole is loaded with the foregoing is true and correct before that the foregoing is true and correct BIGNED **HILLE Reg. Permit Coord** **TITLE Reg. Permit Coord** **TITLE Reg. Permit Coord**	multiple completion on Well on Report and Log form.) Cluding estimated date of starting any depths for all markers and some pertination. O# * packer fluid. luid.*- alve, & pressure The completion on Well alve, & pressure The completion on Well The completion on W

578