

well pad, and all unneeded access roads will be ripped to promote vegetation. Rehabilitation will be accomplished within 90 days after abandonment.

11. OTHER INFORMATION:

- A. Topography: The wellsite is located slightly above the edge of the Caprock. Above the Caprock, the surface is relatively flat sloping gently to the south-southeast at the rate of 50 feet/mile. Below the Caprock, the land slopes more abruptly to the southwest at the rate of 90 feet per mile.
- B. Soil: The surface is rocky (caliche) with a very thin soil cover.
- C. Flora and Fauna: The vegetation cover is generally sparse and consists of mesquite and perennial native range grasses. Wildlife in the area is typical of semi-arid desert land and includes coyotes, rabbits, rodents, reptiles, doves, and quail.
- D. Ponds and Streams: There are no rivers, streams, ponds, or lakes in the area.
- E. Residences and Other Structures: The nearest occupied dwelling is a ranch house one-half mile southwest of the wellsite. The closest water well is also located at the ranch house. Union Texas Petroleum operates a water injection plant one and one-half miles northwest of the drill site.
- F. Archeological, Historical, and Cultural Sites: None observed in the area.
- G. Land Use: Grazing and bird hunting.
- H. Surface Ownership: Well is on surface owned by Nadine Turner of Eunice, New Mexico.

12. OPERATOR'S REPRESENTATIVES:

The field representatives responsible for assuring compliance with the approved Surface Use and Operations Plan are as follows:

Doyle Hartman  
508 C & K Petroleum Building  
Midland, Texas 79701  
Office Phone: 915-684-4011  
Home Phone: 915-694-9526