

well pad, and all unneeded access roads will be ripped to promote vegetation. Rehabilitation will be accomplished within 90 days after abandonment.

11. OTHER INFORMATION:

- A. Topography: The wellsite is located at the base of the Caprock. Above the base of the Caprock, the surface slopes to the south at the rate of 100 feet/mile. At the base of the Caprock, the land slopes more gently to the southwest at the rate of 20 feet per mile.
- B. Soil: The surface is rocky (caliche) with a very thin soil cover.
- C. Flora and Fauna: The vegetation cover is generally sparse and consists of mesquite and perennial native range grasses. Wildlife in the area is typical of semi-arid desert land and includes coyotes, rabbits, rodents, reptiles, doves and quail.
- D. Ponds and Streams: There are no rivers, streams, ponds, or lakes in the area.
- E. Residences and Other Structures: The nearest occupied dwellings are in the City of Jal, one (1) mile northwest of the wellsite. The closest water supply is also located at Jal, New Mexico.
- F. Archelological, Historical, and Cultural Sites: None observed in the area.
- G. Land Use: Grazing and bird hunting.
- H. Surface Ownership: Well is on surface owned by Nadine Owen Turner, Jonnie Mark Owen and Delrose Perry, of Eunice, New Mexico.

12. OPERATOR'S REPRESENTATIVES:

The field representative responsible for assuring compliance with the approves Surface Use and Operations Plan is as follows:

Robert Lansford
908 Cochiti
Hobbs, New Mexico 88240
Business phone: 505-392-5890
Mobile phone: 505-397-3291, Unit 2179.