		N
		P. O. BOX 1980
•	Form 9–331 Dec. 1973	HOBBS, NEW MEXICO A80240 Budget Bureau No. 42-R1424
	UNITED STATES	5. LEASE
	DEPARTMENT OF THE INTERIOR	NM-45706
· .	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
	reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	1. oil gas well other	Federal DD 9. WELL NO.
	2. NAME OF OPERATOR]1
م المنافقة الم	Amoco Production Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Wildcat Morrow
	P. O. Box 68, Hobbs, New Mexico 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR
	4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
	below.) AT SURFACE: 660' FSL X 1980' FEL	34-25-35 12. COUNTY OR PARISH 13. STATE
•	AT TOP PROD. INTERVAL: (Unit 0, SW/4,SE/4) AT TOTAL DEPTH:	Lea NM
		14. API NO.
	16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
		15. ELEVATIONS (SHOW DF, KDB, AND WD) 3165.1 GR
	REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT OFF	
	FRACTURE TREAT	CERTEN
·	SHOOT OR ACIDIZE	
· · ·	PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Ferm 9–330.)
- 	MULTIPLE COMPLETE	AR 3 1983
	ABANDON* (other) Run liner & complete in Strawn	DHL & DES
	Minen	IALS MGMT. SERVICE
	17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly ROSWELL, NEW MEXAGE ails, and give pertinent dat including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations a measured and true vertical depths for all markers and zones pertinent to this work.)*	
1.7.C. 1.7.C. 1.	Propose to run 4" liner as follows:	
	Clean out tubing and displace hole with 14.5	PPG mud. Pull tubing, packer
	and tailpipe. Clean out hole to 14352'. Ci flush joint liner. Set linerat 14352'. Top	rculate hole. Run 4", N-80, 11.6#
	Preflush with 50 barrels Poz mix at 15.2 PPG	of liner approximately 13264'.
	class H cement with .6% Halad 22-A and .4% C	FR-2. WOC 18 hours. Run in hole
	with bit and dress top of liner.Test casing	to 600 psi for 30 min. Clean out
	liner to float shoe. Displace hole to 11,80	0' with 63 barrels 10# 2% KCL brine
and a second	water. Pull out of hole. Run permanent pac casing Run 2-7/8" tubing and profile nipple.	Land tailpipe at $13000'$ Run $A_{-1}/$
	seal assembly and on/off tool. Circulate ho	le with 2% KCL brine water. Perfora
	Strawn intervals 13766'-772', 13792'-796, 13	820'-824', 13845'-848', 13970'-976'
	subs arther Balley Balve! Manu. and ry We Stafford, HOU 1-DI	MF Set @ Ft.
	18. I hereby certify that the foregoing is true and correct	
•	SIGNED TIME - TAMman TITLE Ast. Adm. And	alyst DATE3-1-83
	APPROVED This space for Federal or State of	(fice use)
	(CAIG, SGD.) DAVIND AT AGO	
مر من	CONDITIONS OF APPROVAL, IF ANY: MAR 2 9 1983	DATE
	MMI 2 9 1903	
	HOZJAMES A. GILLHAM	
·····	DISTRICT SUPERVISOR See Instructions on Reverse	S!a

13820'-824, 13845'-848, 70'-976', 13984'-990, 13994'-9 , 14008'-016', 14080'-084', 14124'-128', 14138'-142, 14166'-168', and 14176'-176' with 2 JSPF. Flow test well. If well will not flow run gamma ray temperature survey and acidize with 9000 gallons 15% NEFE HCL. Tag acid with radioactive material. Flush to perfs with 92 barrels 2% KCL brine water. Swab and flow test well.Verbal approval Stewart-Freeman 2-25-83.

MAR 30 1983 HOBSS OFFICE