Submit 3 Copies To Appropriate District Office			
Ullice	State of New M	exico	Form C-103
District 1	Energy, Minerals and Nati	ural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II	OIL CONSERVATION	NOISING	30-025-28407
All CARELE REALEMENTED IN CORE .			5. Indicate Type of Lease
1000 Rio Brazos Rd. Aztec NM 87410			STATE E FEE
District IV Santa Fe, NM 87504		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87504			B-1327
SUNDRY NOT	CES AND REPORTS ON WELLS	ç	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PL	JUG BACK TO A	7. Lease Mame of Onic Agreement Name:
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (FORM C-101) F	OR SUCH	
PROPOSALS.)			LANGLIE JAL UNIT
1. Type of Well: Oil Well ☑ Gas Well [
	Other		
2. Name of Operator KENSON OPERATING	CONDANY THO		8. Well No. 104
	COMPANY INC.		
3. Address of Operator P O BOX 3531, MIDLAND TX 79702			9. Pool name or Wildcat
P O BOX 3531, MIDLAND TX 79702 LANGLIE MATTIX (SRQBG) 4. Well Location			LANGLIE MAIIIX (SKQBG)
4. Wen Location			
Unit Letter M :	140 feet from the SOUT	hline and	247 fortform the Worth in
			247 feet from the <u>west</u> line
Section 32	Township 24S R	ange 37E	NMPM LEA County NM
	10. Elevation (Show whether L		cl
	<u>3230' GR</u>		~ <i>)</i>
11 Check A	ppropriate Box to Indicate N	ature of Notice	Ponort or Other Date
NOTICE OF IN	TENTION TO		
			SEQUENT REPORT OF:
		REMEDIAL WOR	K ALTERING CASING
	CHANGE PLANS	COMMENCE DRI	
		COMMENCE DI	
PULL OR ALTER CASING		CASING TEST AN	
	COMPLETION	CEMENT JOB	
OTHER:		OTUED. Momo	
			orary Abandon 🛛 🔀
12. Describe proposed or comple	ered operations. (Clearly state all	pertinent details, an	d give pertinent dates including actimated date
of monting only proposed work)	CEEDITELLAS E. M. L. L.		a Erre permient dates, merudning estimated date
of starting any proposed work)	. SEE RULE 1103. For Multiple (Completions: Attack	h wellbore diagram of proposed completion
of starting any proposed work) or recompilation.	. SEE RULE 1103. For Multiple (Completions: Attack	h wellbore diagram of proposed completion
of starting any proposed work) or recompilation.	. SEE RULE 1103. For Multiple (Completions: Attack	h wellbore diagram of proposed completion
of starting any proposed work) or recompilation. 6-4-02 RIH with wi	SEE RULE 1103. For Multiple (Completions: Attack	top perf @ 31721) PTH
of starting any proposed work) or recompilation. 6-4-02 RIH with with with 5-1/2	SEERULE 1103. For Multiple (ireline. Set CIBP 'packer. Tested	@ 3100' (top perf @ 3172'). RIH
of starting any proposed work) or recompilation. 6-4-02 RIH with with with 5-1/2	SEE RULE 1103. For Multiple (@ 3100' (h wellbore diagram of proposed completion top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer.
of starting any proposed work) or recompilation. 6-4-02 RIH with with with 5-1/2' hole with p	SEERULE 1103. For Multiple (ireline. Set CIBP ' packer. Tested packer fluid. POH	@ 3100' (@ 3100' (plug to 500 with tubin	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer.
of starting any proposed work) or recompilation. 6-4-02 RIH with with with 5-1/2' hole with F 6-5-02 RIH with 1	SEERULE 1103. For Multiple (ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top	Completions: Attack @ 3100' (plug to 500 with tubin off casing	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer.
of starting any proposed work) or recompilation. 6-4-02 RIH with with with 5-1/2' hole with F 6-5-02 RIH with 1 up to 700#,	SEERULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted	@ 3100' (plug to 500 with tubin off casing for 40 min	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²² Pressur e d
of starting any proposed work) or recompilation. 6-4-02 RIH with with with 5-1/2' hole with F 6-5-02 RIH with 1 up to 700#,	SEERULE 1103. For Multiple (ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top	@ 3100' (plug to 500 with tubin off casing for 40 min	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer.
of starting any proposed work) or recompilation. 6-4-02 RIH with with with with 5-1/2' hole with F 6-5-02 RIH with 1 up to 700#, called but	SEERULE 1103. For Multiple of reline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to	@ 3100' (plug to 500 with tubin off casing for 40 min witness.	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²⁰ Pressured n. NM OCD representative
of starting any proposed work) or recompilation. 6-4-02 RIH with with with with 5-1/2' hole with F 6-5-02 RIH with 1 up to 700#, called but	SEERULE 1103. For Multiple of reline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to	@ 3100' (plug to 500 with tubin off casing for 40 min witness.	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²² Pressure n. NM OCCV representative
of starting any proposed work) or recompilation. 6-4-02 RIH with with with with 5-1/2' hole with F 6-5-02 RIH with 1 up to 700#, called but	SEERULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted	@ 3100' (plug to 500 with tubin off casing for 40 min witness.	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²⁰ Pressured n. NM OCD representative
of starting any proposed work) or recompilation. 6-4-02 RIH with with with with 5-1/2' hole with F 6-5-02 RIH with 1 up to 700#, called but	SEERULE 1103. For Multiple of reline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to	@ 3100' (plug to 500 with tubin off casing for 40 min witness.	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²⁶ 27282930 with fluid, ²⁶ Pressured n. NM OCCOV representative ht project.
of starting any proposed work) or recompilation. 6-4-02 RIH with with with with 5-1/2' hole with F 6-5-02 RIH with 1 up to 700#, called but	SEERULE 1103. For Multiple of reline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to	@ 3100' (plug to 500 with tubin off casing for 40 min witness.	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²⁰ Pressured n. NM OCD representative ht project.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5 6-5-02 RIH with 1 up to 700#, called but TA well for	SEERULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro	Completions: Attack @ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²⁶²⁷²⁸²⁹ n. NM OCOV representative ht project.
of starting any proposed work) or recompilation. 6-4-02 RIH with with with with 5-1/2' hole with F 6-5-02 RIH with 1 up to 700#, called but	SEE RULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro	Completions: Attack @ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²⁶²⁷²⁸²⁹ n. NM OCOV representative ht project.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5-1/2' hole with 1 up to 700#, called but TA well for	see RULE 1103. For Multiple of reline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro	@ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ⁵²⁶ Pressured n. NM OCD representative ht project.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5 6-5-02 RIH with 1 up to 700#, called but TA well for	SEERULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro	Completions: Attack @ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²⁶²⁷²⁸²⁹ n. NM OCOV representative ht project.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5-1/2' hole with 1 up to 700#, called but TA well for I hereby certify that the information SIGNATURE	SEE RULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro	@ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²²⁷²⁸²⁹ n. NM OCD representative nt project.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5-1/2' hole with 1 up to 700#, called but TA well for I hereby certify that the information SIGNATURE	SEE RULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro above is true and complete to the Myount SIRGO, III	@ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ⁵²⁶ Pressured n. NM OCD representative ht project.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5-1/2' hole with 1 up to 700#, called but TA well for I hereby certify that the information SIGNATURE Type or print name M. A. Start ORE	SEE RULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro above is true and complete to the TITLE_ SIRGO, III	@ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluids? Pressure n. NM OCD representative nt project. ge and belief.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5-1/2' hole with 1 up to 700#, called but TA well for I hereby certify that the information SIGNATURE Type or print name M. A. (This space for StatOROS/INAL SIGNAL S	SEE RULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro above is true and complete to the MMO TITLE_ SIRGO, III	@ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen best of my knowled, ENGINEER	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, Pressure n. NM OCD representative ht project. ge and belief.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5-1/2' hole with 1 up to 700#, called but TA well for I hereby certify that the information SIGNATURE Type or print name M. A. (This space for StatOROS/INAL SIGNAL S	SEE RULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro above is true and complete to the MMO TITLE_ SIRGO, III	@ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen best of my knowled, ENGINEER	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluids? Pressure n. NM OCD representative nt project. ge and belief.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5-1/2' hole with 1 up to 700#, called but TA well for I hereby certify that the information SIGNATURE Type or print name M. A. Start ORE State ORE	SEE RULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro above is true and complete to the MMO TITLE_ SIRGO, III	Completions: Attack @ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen best of my knowled ENGINEER	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²⁰ Pressure n. NM OCOV representative ht project. ge and belief.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5-1/2' hole with 1 up to 700#, called but TA well for I hereby certify that the information SIGNATURE Type or print name M. A. (This space for StatOROS/INAL SIGNAL S	SEE RULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro above is true and complete to the MMO TITLE_ SIRGO, III	Completions: Attack @ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen best of my knowled ENGINEER	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²⁰ Pressure n. NM OCD representative ht project. ge and belief.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5-1/2' hole with 1 up to 700#, called but TA well for I hereby certify that the information SIGNATURE Type or print name M. A. (This space for StatOROS/INAL SIGNAL S	SEE RULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro above is true and complete to the MMO TITLE_ SIRGO, III	Completions: Attack @ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen best of my knowled ENGINEER	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²⁰ Pressure n. NM OCD representative ht project. ge and belief.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5-1/2' hole with 1 up to 700#, called but TA well for I hereby certify that the information SIGNATURE Type or print name M. A. (This space for StatOR&DINAL SIGNAL SI	SEE RULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro above is true and complete to the MMO TITLE_ SIRGO, III	Completions: Attack @ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen best of my knowled ENGINEER	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, Pressure n. NM OCD representative ht project. ge and belief.
of starting any proposed work) or recompilation. 6-4-02 RIH with with 5-1/2' hole with 5-1/2' hole with 1 up to 700#, called but TA well for I hereby certify that the information SIGNATURE Type or print name M. A. (This space for StatOR&DINAL SIGNAL SI	SEE RULE 1103. For Multiple of ireline. Set CIBP packer. Tested packer fluid. POH jt. tubing. Top held and charted not available to use in ongoing ro above is true and complete to the MMO TITLE_ SIRGO, III	Completions: Attack @ 3100' (plug to 500 with tubin off casing for 40 min witness. edevelopmen best of my knowled ENGINEER	top perf @ 3172'). RIH 0#, held okay. Circulated ng and packer. with fluid, ²⁶ 27282930 m. NM OCDV representative ht project. ge and belief.