Form 3160-5 (Hovember 1983)	UNITED STATES			No. 1004-0135 1, 1985	
(November 1993) (rother hy 9-331) DEPARTMENT OF THE INTERIOR (Other histracticities on re- BUREAU OF LAND MANAGEMENT			J LD-SE DESIGNATION AN	5. LEASE DESIGNATION AND SERIAL NO. LC067968	
		6 IF INDIAN, ALLOTTEE OR TRIBE NAME			
(Do not use this form	RY NOTICES AND REPOR n for proposals to drill or to deepen or a "APPLICATION FOR PERMIT" for su	plug back to a different reservoir.			
Use	7. UNIT AGREEMENT NAME				
Mar⊡ war⊡	OTHER				
2. NAME OF OPERATOR	& FARM OR LEASE NAME				
OXY	W. DOLLARHIDE	W. DOLLARHIDE QN SD UT			
3 ADDRESS OF OPERATOR P.O. BOX 50250 MIDLAND, TX 79710			9. WELL NO.	s.WELLNO. 76	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface				10. FIELD AND POOL, OR WILDCAT	
			DOLLARHIDE Q	DOLLARHIDE QUEEN	
				11. SEC, T, R, M, OR BLK AND SURVEY OR AREA	
125 FSL 2300 FEL SWSE					
14. PETIMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)				SEC 30 T24S R38E	
14. PETMIT NO.	EL ELEVATIONO (SILVA WIERS DE,	3117	LEA	NM	
30-025-29995	k Appropriate Box To Indicate			1	
Chec	KAPPropriate Box To Indicate		UP OT OTHER Data		
		~			
TESTWATER SHUT-OFF	PULLORALTER CASING	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING V		
	MULTIPLE COMPLETE	SHOOTING OR ACIDIZING	ABANDONM		
SHOOT OR ACIDIZE	CHANGE PLANS	(Other)			
			Its of multiple completion on V completion Report and Log for	• •	
	TD - 3842' PBTD - 3652'	PERFS - 3587' - 3633'			
				-	
	SEE OTHER	SIDE			
				= m	
			<del>ب</del> کړ.		
				õ	
				<u>ں</u>	
18. I hereby certify that the foregoing is true and correct					
SIGNED	TITLE	PROD. ACCT.	DATE	3	
(This space for Federal or State of	the use, D Call-na.				
APPROVED BY	WARTE STATE		DATE		
SEE ATTA	しバレレ *See instruct	ions on Reverse Side			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fradulent statements or representations as to any matter within its jurisdiction.

WDQSU 76 Procedure to TA Page 2

.

- 1. MIRU PU. ND WH. NU BOP. TOOH with tbg. If there is evidence of scale, TIH w/ 4-3/4" RB & 5-1/2" CS to 3652'.
- 2. TIH w/ RTTS pkr on 2-7/8" tbg to 3550'. Pres annulus to 300# for 15 min. Rel pkr & TOOH.
- 3. RIH w/ CIBP on wireline & set @ 3550'. Dump 5 sx (35') cmt on CIBP. TIH w/ production tbg to new PBTD. Circ hole w/ pkr fluid. Pres test to 300# for 15 min. ND BOP. NU WH. TIH w/ rods & clamp off. RD PU.

WDQSU 76 is being temporarily abandoned because it produces .5 BO + 1320 BWPD. We do not wish to plug this well at this time because enhanced oil recovery is being considered for this Unit. This wellbore may be utilized when such a project is implemented.

- -

(Rev. 9-30-92)

## BUREAU CF LAND MANAGEMENT CARLSBAD RESOURCE AREA

## Temporary Abandonment of Wells on Fegeral Lands

Conditions of Approval

According to 43 CFR 3162.3-4-c. " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open noile.
- 3. All downnole production/injection equipment (tuping, rods. etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 ps1. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits a subsequent Sunory Notice requesting TA approval.
- 2. Attacnes a clear copy or the original of the pressure test chart,
- 3. And explains why such a well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative.

If the well does not pass the casing integrity test, then the operator snall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandom the weil.