

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30014
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-9519
7. Lease Name or Unit Agreement Name	West Dollarhide Queen Sand Unit
8. Well No.	83
9. Pool name or Wildcat	Dollarhide Queen

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Sirgo Operating, Inc.	
3. Address of Operator P.O. Box 3531, Midland, Texas 79702	
4. Well Location Unit Letter E : 1700 Feet From The North Line and 1000 Feet From The West Line Section 29 Township 24S Range 38E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3213' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-12-90 MI&RU PU. POH w/pump & rods. Unset tbg anchor. POH w/tbg & tbg anchor. RIH w/ 5-1/2" csg scraper & bit to 4044'. RU & circ hole w/2% KCL. POH w/bit, scraper & tbq SION.

3-13-90 RIH w/tail jt, SN & 2-7/8" tbg. Set tail jt @ 3764', SN @ 3733' & tbg @ 3731'. RIH w/2-1/2" x 2" x 16' RWAC pump & BHA. Space out & hang on. Saddle bearing locked up. SI.

3-14-90 Repair saddle bearing.

3-15-90 Install saddle bearing. Space out & hang on. Start pumping.

3-16/29-90 Testing

3-30-90 TEST: 3 BO 60 BW .5 MCF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Atwater TITLE Production Technician DATE 4-10-90

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE APR 13 1990

CONDITIONS OF APPROVAL, IF ANY: