Submit 3 copies to Appropriate District Office	State of New M Ener, linerals and Natural Re		Form C- Revised		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II	OIL CONSERVATIO P.O. Box 2088 Santa Fe, New Mexico	3	WELL API NO. 30 025 30822 5. Indicate Type of Lease		
P.O. Box Drawer DD, Artesia, NM 88210 DISTRICT III	Salita re, new mexico	07504-2088			
1000 Rio Brazos Rd., Aztec, NM 87410			B-9613		
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESE	TICES AND REPORTS ON WEL POSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PI C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT		
1. Type of Well: OIL GAS WELL WEI					
2. Name of Operator TEXACO EX	PLORATION & PRODUCTION INC.		8. Well No. 100		
3. Address of Operator P.O. BOX 730, HOBBS, NM 88240			9. Pool Name or Wildcat DOLLARHIDE TUBB DRINKARD		
4. Well Location Unit Letter M Section 29	<u>1169</u> Feet From The <u>SOUT</u> Township <u>24S</u> R	H Line and <u>120</u> ange <u>38E</u> NM	Feet From TheWESTLine		
10. Elevation (Show whether DF, RKB, RT,GR, etc.) GR-3160', KB-3174'					
11. Check A	ppropriate Box to Indicate Nat	ure of Notice, Report	, or Other Data		
NOTICE OF INTENTION	ON TO:	SL	IBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON I CHANGE PLANS I	REMEDIAL WORK	ALTERING CASING CASING CASING PLUG AND ABANDONMENT		
PULL OR ALTER CASING	S & STIMULATE	CASING TEST AND CEMEN OTHER:	T JOB		

 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Objective: Texaco intends to add Drinkard perforations and then perform a fracture stimulation.

1. RUPU. Install BOP. TOH with production equipment.

2. Clean out with bailer to 6650'.

3. Perforate with 8 JSPF from 6550' - 6560'.

4. TIH with CIBP and set @ 6640'. Cap with 10' cement. TIH with packer and set @ 6350'. Load backside and hold 1000#.

5. Fracture perfs from 6448' - 6581' with 68000g 40# Spectra + 180000# 20/40 sand. AIR = 40 BPM, Pmax = 8000#.

6. Release packer and TOH with treating tubing. TIH with bit and clean out to CIBP. TIH with tubing.

7. Place well on production.

Thereby certify that the information above is tructed complete to the best my knowledge and belief. SIGNATURE	DATE2/8/95
TYPE OR PRINT NAME Darrell J. Carriger	Telephone No. 397-0426

(This space for State Use)	ORIGINAL SIGNED BY JERRY SEX	TON
APPROVED BY	DISTRICT I SUPERVISOR	TITLE_

_

CONDITIONS OF APPROVAL, IF ANY:

DeSoto/Nichols 10-94 ver 2.0

