

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1167
7. Lease Name or Unit Agreement Name Langlie A State
8. Well No. 2Y
9. Pool name or Wildcat Jalmat Tansil Yates 7-Rvrs Gas

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Meridian Oil Inc.	
3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810	
4. Well Location Unit Letter H : 1980 Feet From The North Line and 735 Feet From The East Line Section 36 Township 24S Range 36E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RIH with chemical cutter and cut tubing @ 2800'. RIH w/casing scraper to top of fish, POOH. Set cmt. retainer on tubing @ +/- 2600'. Squeeze with 100 sx. Sting out of retainer and cap with 2 sx. Pull up and circ. hole with 9 ppg gelled brine.

Pull up to 1300', set a plug across the top of the salt at 1180' - 1300'. (15 sx).

Perf 4 squeeze hole @ 410'. Open braidenhead valve and pump 150 sx Cl. C down casing. Allow cmt to circ out braidenhead. Cut off casing 3' below ground level and install P&A marker. Rip and restore location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Connie Malik TITLE Reg. Compliance Rep. DATE 4/1/92

TYPE OR PRINT NAME Connie Malik TELEPHONE NO. 915-688-6898

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

APR 07 '92