Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR N. M. OIL CONS. COMMISSION

FORM APPROVED Budget Bureau No. 1004-0135

D11D D 4 11 OF 1	P 0 ROY 1000	Expires: March 31, 1993
BUREAU OF	HOBBS MEN MENO	5. Lease Designation and Serial No.
BUREAU OF LAND MANAGEMENT. O. BOX 1980 HOBBS. NEW MEXICO SUNDRY NOTICES AND REPORTS ON WELLS		88240 NM-037667
Do not use this form for proposals to drill or to deepen or reentry to a different reservo		
	R PERMIT—" for such proposals	orr.
	The second proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
Type of Well		
Oil Gas Other		8. Well Name and No.
2 Name of Onerator		Myers B Federal RA/B#
Amoco Production Company		9. JAPI Well No.
3 Address and Telephone No.		30-025-11024 10. Field and Pool, or Exploratory Area
ν. 0. Box 3092 (Rm 17.182) Houston		
Location of Well (Footage, Sec., T., R., M., or Survey Description)		Jalmat- iates - Gas
660 FNL & 1980 FEL, Sec 6, T-24-S, R-37-E		11. County or Parish, State
(Unit Ltr3)		Lea NM
CHECK APPROPRIATE BOX	a) TO INDICATE MATURE OF MOTIOE DES	
CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REF	OHI, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	NC
Notice of Intent	Abandonment	Change of Plans
_	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water (Note: Report results of multiple completion on Well
13. Describe Described Occurrence (Clearly approx		Completion or Recompletion Report and Log form 1
give subsurface locations and measured and true vertice	Il pertinent details, and give pertinent dates, including estimated date of state all depths for all markers and zones pertinent to this work.)*	- 10 전 10 전 10 H 10 H 10 H 10 H 10 H 10 H
2000 1200 1200 1200 1200 1200 1200 1200	Mar. 55	The state of the s
1. RUSU KPOH WIDUAL P		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2. SET CIBP AT3330 X CA	IP W135'CMT	- A
5 COM 11/11 To 10 00 1		ن دن
3, SPOT MUD TO 2950'		*** (17)
	1P N1 35'CMT	
4. SET CIBP AT 2950 x CA	IP N/35'CMT	E CO
4. SET CIBP AT 2950 XCA 6. LOAD HOLE WI MUD		
4. SET CIBP AT 2950 X CA 6. LOAD HOLE WI MUD 6. PERFORATE AT 1260.	SET CMT GETAINER AT 1160'	<u> </u>
4. SET CIBP AT 2950 X CA 6. LOAD HOLE WI MUD 6. PERFORATE AT 1260.		<u> </u>
4. SET CIBP AT 2950 X CA 6. LOAD HOLE WI MUD 6. PERFORATE AT 1260. 7. FUMP 100' CMT PLUS II	SET CMT RETAINER AT 1160' aside AND OUTSIDE OF THE 7"CS	<u> </u>
4. SET CIBP AT 2950 X CA 6. LOAD HOLE WI MUD 6. PERFORATE AT 1260.	SET CMT RETAINER AT 1160' aside AND OUTSIDE OF THE 7"CS	<u> </u>
4. SET CIBP AT 2950 X CA 6. LOAD HOLE WI MUD 6. PERFORATE AT 1240. 7. PUMP 100' CMT PLUG II 8. CAP WI 15 SX CMT PL	SET CMT RETAINER AT 1160' INSIDE AND OUTSIDE OF THE 7"CS.	<u> </u>
4. SET CIBP AT 2950 X CA 6. LOAD HOLE WI MUD 6. PERFORATE AT 1240. 7. PUMP 100' CMT PLUG II 8. CAP WI 15 SX CMT PL	SET CMT RETAINER AT 1160' INSIDE AND OUTSIDE OF THE 7"CS.	<u> </u>
4. SET CIBP AT 2950 X CA 6. LOAD HOLE WI MUD 6. PERFORATE AT 1260. 7. FUMP 100' CMT PLUS II	SET CMT RETAINER AT 1160' INSIDE AND OUTSIDE OF THE 7"CS.	<u> </u>
4. SET CIBP AT 2950 X CA 6. LOAD HOLE WI MUD 6. PERFORATE AT 1240. 7. PUMP 100' CMT PLUG II 8. CAP WI 15 SX CMT PL	SET CMT RETAINER AT 1160' INSIDE AND OUTSIDE OF THE 7"CS.	<u> </u>
4. SET CIBP AT 2950 X CA 6. LOAD HOLE WI MUD 6. PERFORATE AT 1240. 7. PUMP 100' CMT PLUG II 8. CAP WI 15 SX CMT PL WEU BORE SKETCH ATTACA	SET CMT RETAINER AT 1160' INSIDE AND OUTSIDE OF THE 7"CS.	<u> </u>
4. SET CIBP AT 2950 x CA 5. LOAD HOLE WI MUD 6. PERFORATE AT 1240. 7. PUMP 100' CINT PLUG II 8. CAP WI 15 SX CIMT PL WELL BORE SKETCH ATTACA 4. I hereby certify that the foregoing is true and correct 11 12	SET CMT RETAINER AT 1160' INSIDE AND CUTSIDE OF THE 17" CS. LUG AT SURFACE	5 FROM 1260'-1160'
4. SET CIBP AT 2950 x CA 5. LOAD HOLE WI MUD 6. PERFORATE AT 1240. 7. PUMP 100' CMT PLUG II 8. CAP WI 15 SX CMT PL WELL BORE SKETCH ATTACA 4. I hereby certify that the foregoing is true and correct Signed Lewisia. M. Minich	SET CMT RETAINER AT 1160' INSIDE AND CUTSIDE OF THE 17" CS. LUG AT SURFACE WELL Title Staff Assistant	SFROM 1260'-1160' Date 6-9-93
4. SET CIBP AT 2950 x CA 6. LOAD HOLE WI MUD 6. PERFORATE AT 1240. 7. PUMP 100' CINT PLUG II 8. CAP WI 15 SX CIMT PL WELL BORE SKETCH ATTACA	SET CMT SETAINER AT 1160' CASIDE AND CUTSIDE OF THE 17" CS. CLUG AT SURFACE HED Title Staff Assistant	SFROM 1260'-1160' Date 6-9-93

Approved by Conditions of approval, if any

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any faise, fictitious or fraudulent statements or representations as to any matter wi

ju 4.1. 1993