Submit 3 Copies to Appropriate

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

DISTRICT! OIL CONSEDIVATION DIVISION	
P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION	
P.O. Box 2088	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210  Santa Fe, New Mexico 87504-2088	30-025-11033
DISTRICT III	5. Indicate Type of Lease  STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
OLINIORYMATERIA	N/A
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT HESERVOIR. USE APPLICATION FOR PERMIT	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)  Type of Well:	
OL	Toby
Name of Operator	
Energy Development Corporation	8. Well No.
Address of Operator	9. Pool name or Wildcat
1000 Louisiana, Suite 2900, Houston, TX 77002	Langlie-Mattix Seven Rivers Of
Well Location	
Unit Letter L : 1980 Feet From The South Line and 629	Feet From The West Line
•	
Section Township 24S Range 37E  10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM Lea County
3323 GR	
Check Appropriate Box to Indicate Nature of Notice, Re	anost on Other Date
NOTICE OF INTENTION TO:	CEOLIENT DEDOCT OF
	SEQUENT REPORT OF:
REFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
APORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	
LOGALTER CASING	
	MENT MODIL
CASING TEST AND CE	ment wb
CASING TEST AND CE	
ICD.	
Describe Proposed or Completed Operations (Clearly state all pertinent details and airs pertinent data in the	ing estimated date of starting any proposed
Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, include work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wirelin w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casin	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includ work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wirelin w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casin under packer, displacing cement to 265'. WOC 4 h	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includ work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wirelin w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casin under packer, displacing cement to 265'. WOC 4 h 20 sx cement from 62' to surface.	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includ work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wirelin w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casin under packer, displacing cement to 265'. WOC 4 h	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wireling w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casing under packer, displacing cement to 265'. WOC 4 in 20 sx cement from 62' to surface.	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wireling w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casing under packer, displacing cement to 265'. WOC 4 in 20 sx cement from 62' to surface.	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wireling w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casing under packer, displacing cement to 265'. WOC 4 in 20 sx cement from 62' to surface.	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wireling w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casing under packer, displacing cement to 265'. WOC 4 in 20 sx cement from 62' to surface.	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wireling w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casing under packer, displacing cement to 265'. WOC 4 in 20 sx cement from 62' to surface.	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wireling w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casing under packer, displacing cement to 265'. WOC 4 in 20 sx cement from 62' to surface.	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includ work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wirelin w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casin under packer, displacing cement to 265'. WOC 4 h 20 sx cement from 62' to surface.  1-19-95 Cut off wellhead; weld on Dry Hole Marker.	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wireling w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casing under packer, displacing cement to 265'. WOC 4 in 20 sx cement from 62' to surface.  1-19-95 Cut off wellhead; weld on Dry Hole Marker.	ing estimated date of starting any proposed  the @ 3400'. Circulated hole  ag @ 400'. Squeezed 55 sx cement  nours. Tagged plug @ 262'. Pump
Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, include work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wireling w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casing under packer, displacing cement to 265'. WOC 4 in 20 sx cement from 62' to surface.  1-19-95 Cut off wellhead; weld on Dry Hole Marker.	ing estimated date of starting any proposed  se @ 3400'. Circulated hole
Describe Proposed or Completed Operations (Clearly state all periment details, and give pertiment dates, include work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wireling w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casing under packer, displacing cement to 265'. WOC 4 in 20 sx cement from 62' to surface.  1-19-95 Cut off wellhead; weld on Dry Hole Marker.	ing estimated date of starting any proposed  the @ 3400'. Circulated hole  ag @ 400'. Squeezed 55 sx cement  nours. Tagged plug @ 262'. Pump
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includ work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wireling w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casing under packer, displacing cement to 265'. WOC 4 in 20 sx cement from 62' to surface.  1-19-95 Cut off wellhead; weld on Dry Hole Marker.	ing estimated date of starting any proposed  The @ 3400'. Circulated hole  The age and age and age and age and age and age and age
Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, include work) SEE RULE 1103.  1-17-95 POOH w/production equipment. Set CIBP on wireling w/10# mud.  1-18-95 Pumped 25 sx cement 3400-3255'. Perforated casing under packer, displacing cement to 265'. WOC 4 in 20 sx cement from 62' to surface.  1-19-95 Cut off wellhead; weld on Dry Hole Marker.	erintendent DATE 2-13-95  TELEPHONE NO. 713/750-73