Submit 3 Copies To Appropriate District State of New Mexico	Form C-1
Critice Energy, Minerals and Natural Resources	Revised March 25, 19
District I 1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II OIL CONSERVATION DIVISION	30-025- 1040
811 South First, Artesia, NM 87210 District III 2040 South Pacheco	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE 🗌 FEE 🔀
<u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505	 6. State Oil & Gas Lease No. 8910138170 -
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	Myers Langlie Mattix Unit
1. Type of Well:	
Oil Well S Gas Well Other	8. Well No.
2. Name of Operator OXY USA WTP Limited Partnership 19246	77(-
OXY USA WTP Limited Partnership 19246. 3. Address of Operator	9. Pool name or Wildcat
P.O. Box 50250 Midland. TX 79710-0250	Langlie Mattix 7Rvr Qn-GB
Well Location	
Unit Letter <u>J</u> : 1980 feet from the <u>south</u> line and <u>19</u>	180 feet from the cast lin
Section 7 Township 24 Range 37	NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, etc.	
11. Check Appropriate Box to Indicate ₁ Nature of Notice,	Report or Other Data
	SEQUENT REPORT OF:
ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
EMPORARILY ABANDON 🗌 CHANGE PLANS 🔲 COMMENCE DRILLI	NG OPNS. Development PLUG AND ABANDONMENT
ULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION CEMENT JOB	
	Status
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and gi	ve pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompilation.	wellbore diagram of proposed completion
or recompilation.	
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible	future use.
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible	
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3248</u> Perfs- <u>34に-3585</u> Pkr /CI	future use.
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3548</u> Perfs- <u>34(9-3585</u> Pkr /CI 1. Notify BLM /NMOCD of casing integrity test 24hrs in advance.	future use. BP- <u>3333'</u>
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3298</u> Perfs- <u>34(9-3585</u> Pkr /CI 1. Notify PLM /NMOCD of casing integrity test 24hrs in advance. 2. RU pump truck <u>12203</u> , circulate well with treated water, press	future use. 3P- <u>3333'</u>
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3298</u> Perfs- <u>34(9-3585</u> Pkr /CI 1. Notify BLM /NMOCD of casing integrity test 24hrs in advance. 2. RU pump truck <u>12203</u> , circulate well with treated water, press to 480 # for 30 min.	future use. BP- <u>3333'</u> ure test casing <u>Rund</u> ED Hobbs
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3298</u> Perfs- <u>34(9-3585</u> Pkr /CI 1. Notify BLM /NMOCD of casing integrity test 24hrs in advance. 2. RU pump truck <u>12203</u> , circulate well with treated water, press to 480 # for 30 min.	future use. BP- <u>3333'</u> ure test casing <u>Rund</u> ED Hobbs
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3298</u> Perfs- <u>34(9-3585</u> Pkr /CI 1. Notify PLM /NMOCD of casing integrity test 24hrs in advance. 2. RU pump truck <u>12203</u> , circulate well with treated water, press	future use. BP- <u>3333'</u> ure test casing <u>Rund</u> ED Hobbs
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3298</u> Perfs- <u>34(9-3585</u> Pkr /CI 1. Notify PLM /NMOCD of casing integrity test 24hrs in advance. 2. RU pump truck <u>12203</u> , circulate well with treated water, press to 480 # for 30 min.	future use. BP- <u>3333'</u> ure test casing <u>Rund</u> ED Hobbs
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3298</u> Perfs- <u>39(9-3585</u> Pkr/CI 1. Notify <u>PLMT/NMOCD of casing integrity test 24hrs in advance.</u> 2. RU pump truck <u>12205</u> , circulate well with treated water, press to <u>480</u> # for 30 min.	future use. BP-3333 ure test casing R_{L} ED Hobbs OCD
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3298</u> Perfs- <u>34(9-3585</u> Pkr /CI 1. Notify <u>BLMT/NMOCD</u> of casing integrity test 24hrs in advance. 2. RU pump truck <u>12203</u> , circulate well with treated water, press to <u>480</u> # for 30 min. Expires	future use. BP-3333 ure test casing ED Hobbs OCD
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3298</u> Perfs- <u>3995</u> Pkr/CI 1. Notify <u>BLMT/NMOCD</u> of casing integrity test 24hrs in advance. 2. RU pump truck <u>12203</u> , circulate well with treated water, press to <u>480</u> # for 30 min. Fearporar 4bancomment Expires	future use. BP-3333 ure test casing F_{L} ED Hobbs 000
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3298</u> Perfs- <u>34(9-3585</u> Pkr/CI 1. Notify <u>PLM</u> /NMOCD of casing integrity test 24hrs in advance. 2. RU pump truck <u>1/22/03</u> , circulate well with treated water, press to <u>480</u> # for 30 min. Enclose the performance of the perform	future use. BP-3333 ure test casing $Hobbs$ 3/4/08 Malyst DATE $2(5/03)$ Telephone No. 915-685-5717
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3298</u> Perfs- <u>34(9-3585</u> Pkr/CI 1. Notify <u>PLM</u> /NMOCD of casing integrity test 24hrs in advance. 2. RU pump truck <u>1/22/03</u> , circulate well with treated water, press to <u>480</u> # for 30 min. Enclose the performance of the perform	future use. BP-3333 ure test casing ED Hobbs 3/4/08 Malyst DATE $2(50)$ Telephone No. 915-685-5717 H/STAFF MANAGER
or recompilation. OXY USA WTP LP requests to temporarily abandon this well for possible TD- <u>3585</u> PBTD- <u>3246</u> Perfs- <u>34(9-3585</u> Pkr/CI 1. Notify <u>PKM</u> /NMOCD of casing integrity test 24hrs in advance. 2. RU pump truck <u>1/22/03</u> , circulate well with treated water, press to <u>400</u> # for 30 min. Ereby certify that the information above is true and complete to the best of my knowledge and belief BNATURE <u>Maddate</u> <u>TITLE Sr. Regulatory A</u> be or print name David Stewart	future use. BP-3333 ure test casing $Hobbs$ 3/4/08 Malyst DATE $2(5/03)$ Telephone No. 915-685-5717