Submit 3 Copies to Appropriate District Office	State of I Energy, Minerals and Na					m C-103 rised 1-1-89
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERV 2040 Pache Santa Fe,	co St.		WELL API NO. 30-025-11041		
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	Santa r e,		505	₅Indicate Type of Lea	ise	5 77
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410				•State Oil & Gas Lea	STATE	FEE 🔀
(DO NOT USE THIS FORM FOR DIFFERENT RE	OTICES AND REPORTS OF PROPOSALS TO DRILL OR TO D SERVOIR. USE "APPLICATION F M C-101) FOR SUCH PROPOSALS	EEPEN (OR PER	OR PLUG BACK TO A	7Lease Name or Uni Liberty Royalties		
۲. ۵۱L GAS WELL WELL VELL ♦						
Name of Operator Doyle Hartman				⊪Well No. 5		
aAddress of Operator P.O. Box 10426, Midland, Tx 79702				Pool name or Wildcat Jalmat (T-Y-7R) Pro Gas		
+Well Location		· · · ·				
Unit Letter <u>J</u> : <u>165</u>	0_ Feet From TheSout	<u>1</u>	Line and 1650	Feet From The	East	Line
7 Section 24	S Township 37E	E R	ange	NMPM	Lea	County
	•Elevation (Show whe 3304' GR	ther DF, F	RKB, RT, GR, etc.)			
11 Check	Appropriate Box to Indica	ate Na	ture of Notice, Rep	oort, or Other D	Data	_
NOTICE OF	SEQUENT RE	PORT OF:	;			
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CAS	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OF	PNS.	PLUG AND ANB	
PULL OR ALTER CASING			CASING TEST AND CEME	NT JOB		
OTHER: Return well to beneficial use			OTHER:			[]

¹²Describe Proposed or Completed Operations (*Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work*) SEE RULE 1103.

For Details of Proposed Well Work, please refer to page 2 of 3 and 3 of 3 attached hereto, and made a part hereof.

SIGNATURE CLARCE CORC	TITLE Engineer		DATE 12-11-01	
TYPE OR PRINT NAME Steve Hartman			TELEPHONE NO. 915-694-4011	
(This space for State Use)		Phile Prover by		
APPROVED BY	TITLE	Tr. Of EU.; - Contraction	DATE	

٩.

Page 2 of 3 NMOCD Form C-103 dated 12-11-01 Doyle Hartman Liberty Royalties No. 5 J-7-24S-37E API No. 30-025-11041

Details of Proposed Well Work

We propose mechanically testing wellbore and returning wellbore to beneficial use, by performing the following well work:

- 1. Move in and rig up well service unit.
- 2. Pull and lay down old 2 3/8" O.D. tubing.
- 3. Run 2 7/8" O.D., 6.5 lb/ft, N-80 work string equipped with 5 ¹/₂" Model "C" RBP and 5 ¹/₂" Model "C" packer.
- 4. Pressure test 5 ¹/₂" O.D. casing.
- 5. Repair 5 ¹/₂" O.D. casing, as necessary.
- 6. Run bottom-hole fishing assembly. Latch onto and pull uncemented 3 ¹/₂" O.D. slotted liner.
- 7. Clean out Jalmat open-hole interval.
- 8. Under-ream productive open-hole interval, to a 6" hole diameter.
- 9. Run 4 ¹/₂" O.D., 11.6 lb/ft, J-55 flush-joint liner, equipped with float shoe and float collar.
- 10. Release from liner and pull liner-setting tool.
- 11. Run tubing and 5 ¹/₂" Model "C" packer. Set 5 ¹/₂" packer above liner top.
- 12. Squeeze liner at a cementing rate of 12 BPM to 14 BPM, with 900 sx of API Class "C" cement containing 2.5% CaCl₂, followed by 100 sx of API Class "C" Neat cement. Pull 5 ¹/₂" Model "C" packer.
- 13. Run bottom-hole drilling assembly. Drill out cement, to bottom of 4 ¹/₂" O.D. flush-joint liner.
- 14. Pressure test 5 1/2" O.D. casing and 4 1/2" O.D. liner.
- 15. Rig up Schlumberger. Log well with VDCBL-GR-CCL log and DS-CNL-GR-CCL log.

Page 3 of 3 NMOCD Form C-103 dated 12-11-01 Doyle Hartman Liberty Royalties No. 5 J-7-24S-37E API No. 30-025-11041

- 16. Lay down 2 7/8" O.D. work string. Run new 2 3/8" O.D. production string.
- 17. Perforate, acidize, and frac Jalmat gas interval.
- 18. Return well to beneficial use, as active Jalmat producer.