

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

**U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
LAND CONSERVATION DIVISION**
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	For <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-2431	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation		8. Farm or Lease Name J. R. Holt (NCT-A)
3. Address of Operator P. O. Box 670, Hobbs, NM 88240		9. Well No. 5
4. Location of Well UNIT LETTER <u>0</u> <u>810</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>24S</u> RANGE <u>37E</u> N.M.P.M.		10. Field and Pool, or Wildcat Langlie Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3235' GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with production equipment. Set CIBP at 3240', cap with 35' cement. Fill hole with abandonment mud. Cut and pull casing. Spot 100' plug 2400'-2300'; 161' plug 1240'-1079'; 100' plug across casing stub. Tag casing shoe and stub plugs per OCD request. Spot 50' surface plug. Install dry hole marker. Clean and clear location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.D. Prite TITLE Area Engineer DATE 12-15-82

APPROVED BY ORIGINAL SIGNED BY TITLE JERRY SEXTON DATE DEC 20 1982
CONDITIONS OF APPROVAL, IF ANY: DISTRICT 1 SUPR.

RECEIVED

DEC 17 1982

O. R. R.
HONOLULU OFFICE