

CONTINGENCY AND EVACUATION PLAN
Dusty Mac Resources Inc.
Madera "24" Federal Well No. 1
Lea County, New Mexico

III. TREATMENT OF HYDROGEN SULFIDE POISONING

- A. Remove the patient to fresh air, call physician or ambulance if possible.
- B. If breathing is labored, or has ceased, give artificial respiration immediately. Continue until physician is available, even if person appears to be not breathing. Should disaster conditions make it impossible to move to fresh air, keep your mask on and use resuscitator on patient.
- C. If giving artificial respiration, and patient is breathing, use resuscitator to help eliminate H_2S from the bloodstream.
- D. Keep patient at rest and prevent chilling.
- E. Get patient to a physician as soon as possible.

IV. BLOWOUT PREVENTION MEASURE DURING DRILLING AND COMPLETION

A. Blowout preventor requirements:

All BOP Equipment shall meet (Dusty Mac Resources Inc.) specification as to materials acceptable for H_2S service. This will be tested to full working pressure on initial installation and at any time a seal has been broken, a leak experienced or a known H_2S bearing formation is to be completed. Mechanical operation of all BOP components will be tested daily.

B. String components requirements:

All string components are to be of material that meets (Dusty Mac Resources Inc) specifications for H_2S service. All string components will be inspected prior to running in well. Corrosion will be monitored by coupons to protect the string.

RECEIVED

MAR 30 1961

OFFICE OF
THE ATTORNEY GENERAL