

CONTINGENCY AND EVACUATION PLAN

Dusty Mac Resources Inc.
Madera "24" Federal Well No. 1
Lea County, New Mexico

Designation of Responsibility:

In order to assure the proper execution of this plan, it is essential that one person is responsible for, and in complete charge of implementing these procedures. Therefore, responsibility shall be designated in the following order, depending on who is on location:

1. The Company's Representative (Foreman or Consultant)
2. Contract Toolpusher

Definition of Warning Signs:

Condition: GREEN - Normal Operations - With Caution - Potential Danger

1. Be alert for a change in condition warning sign.
2. Before a zone has been perforated.
3. After a zone has been plugged and pressure tested.

Condition: YELLOW - Danger

1. Anytime a well has been perforated in a known H₂S zone.
2. Circulating same zone.
3. Circulating gas out of zone.
4. When swabbing known H₂S zone.
5. When testing a zone.
6. When performing DST.

Condition: RED - Extreme Danger

1. Uncontrollable well.

After any accidental release of potentially hazardous volume of hydrogen sulfide gas, this program shall be initiated immediately.

1. Set off alarm. Evacuate all persons off location to "safe" briefing area: that is up-wind. Check that all persons are present. If not, proceed with evacuation from hazardous area in the following manner.