

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32568
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	COOPER JAL UNIT
8. Well No.	406
9. Pool Name or Wildcat	JALMAT
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3303'

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter H ; 2522 Feet From The NORTH Line and 400 Feet From The EAST Line
Section 24 Township 24-S Range 36-E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ADD PERFS & ACIDIZE, PLUG BACK LANGLEIE M ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU, POOH W/RODS, NU 3000# BOP. POOH W/TUBING.
2. MIRU WIRLEINE. TIH W/ 5.5" CIBP AND SET @ 3400'(TOP OF PERFS @ 3435'). DUMP 35' CMT ON CIBP NEW PBTD 3365'.
3. TIH W/ 5.5" RBP AND SET @ 3125'(TOP OF PERFS @ 3132'). LOAD HOLE.
4. TIH W/4" 20.2 GRAM CSG GUN ON 120 DEG SPIRAL @ 4JSPF, .40" HOLE DIAMETER AND PERFORATE THE FOLLOWING:
3018'-3022', 3030'-3040', 3057'-3063', 3066'-3084', 3100'-3112', 45' NET 180 HOLES.
5. RD WIRELINE.
6. TIH, TEST TBG TO 3000#, SET PKR @ 2950'. TEST PKR @ 1000#.
7. RU DS, ACIDIZE JALMAT PERFS (PICKLE JOB) W/300 GALS 15% HCL & 150 GALS XYLENE.(ACID JOB) W/3000 GALS 15% HCL NEFEW 250 BS.
8. SD, RD DS.
9. POOH WITH TBG. PULL RBP AND PUT ON PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paula S. Ives TITLE Engineering Assistant DATE 5/6/96

TYPE OR PRINT NAME Paula S. Ives Telephone No. 397-0432

(This space for State Use) **ORIGINAL SIGNED BY DEPT. CLERK**

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE MAY 08 1996

CONDITIONS OF APPROVAL, IF ANY:

