ILLEGIBLE

[illegible]

Communication was established by running 1½" tbg. in the Drewman and setting a packer below the leak. Our recent packer leakage test indicates that either the packer or tbg. is now leaking. This will have to be eliminated or I am to submit acceptable packer leakage test by October 25, 1968.

From the production history shown on the attached plat as shown by the two available wells to be severely drained by the offsetting Texaco wells. Based on a geological analysis by Vic Inman, our well should be structurally and productively between the two Texaco wells. The CC #1 was producing 30% water when [illegible] Texaco wells [illegible] status. With artificial lift we could reasonably expect