OCD Photos and notes from witnessed sampling on 5/13/2025

323-A
Hilcorp Energy Company
MOORE LS 6B LANDFARM
LAT: 36.95101 LONG: -108.04544
UL: O, SEC. 25, T032N, R12W
LANDFARM EXPIRATION DATE:2/27/2028
SMALL LANDFARM REGISTRATION NO. NM 3-4
EMERGENCY NUMBER: 505-324-5170 OR 911
NO SMOKING NO TRESPASSING

Received by OCD: 5/14/2025 7:05:58 AM

Hilcorp Energy Company
MOORE LS 6B LANDFARM
LAT: 36.95101 LONG: -108.04544
UL: O, SEC. 25, T032N, R12W
LANDFARM EXPIRATION DATE:2.27.2028
SMALL LANDFARM REGISTRATION NO. NM 3-4
EMERGENCY NUMBER: 505-324-5170 OR 91
NO SMOKING NO TRESPASSING

Released to Imaging: 5/14/2025 7:53:41 AM

Hilcorp Energy Company
MOORE LS GS LANDFARM
LAT: 36.95101 LONG: -108.04344
SEC. 8, SEC. 21, T32N, R12W
LANDFARM EXPIRATION DATE 2 27 2030
NMOCD LANDFARM REGISTRATION NO. NM 12

Hilcorp Energy Company

MOORE LS 6B

3810038250 NMNM-73439

API NO. 30-045-33564

SWSE, 660' FSL & 2340' FEL

SEC.25 T032N R012W NMPM

SAN JUAN COUNTY, NM ELEV 6386

LAT 36° 57' 04" LONG 108° 02' 46"

EMERGENCY NUMBER (505) 324-5170

NO SMOKING NO TRESPASSING

Received by OCD: 5/14/2025 7:46:54 AM



PC
160
LC

Received by OCD: 5/12/2021 7:56:54 AM

Released to Imaging: 5/12/2021 7:58:37 AM

Received by OCD: 5/18/2023 7:53:41 AM

Released to Imaging: 5/18/2023 7:53:41 AM

Received by OCD: 5/7/2025 7:53:41 AM

Released to Imaging: 5/7/2025 7:53:41 AM

Received by OCD: 11/10/2021 10:49:58 AM

Received by OCD: 5/14/2025 7:40:50 AM

5/13/2025

nAPP2206058318 Moore LS 6B (30-045-30564)

Sampling scheduled @ 9 AM

remediation plan

SVE ⇒ dig + haul ⇒ Small LF

deepest contamination =

15-17' bgs near

bgt.

* Site not ready to sample by 1130. ok'd verbally that sampling can be completed. told them a grab sample from discolored soil under BGT + gray soil on W-wall need to be collected. If sampling ☒14-variance sent to me via email for C-141 N.

Left office 930 - roads in ore terrible ruts are ~1' deep in some areas. may contact BZM.

Arrive @ Moore LS 6B @ 955 - earthwork contractors onsite

took photos of site. - Enterprise encroachment monitor on-site

LF does not have any contaminated soil in cells yet - does have LF sign (photographed)

excavation of former battery is approximately 24' deep. still failing on E-SE corner per earth work contractor

Hilcorp

~~Enviro-Consultants~~ on-site @ approximately 905

Ensolum onsite @ approximately 9:27

Earthwork contractor started spreading soils in LF @ approximately 930

Chad

Cody (Hilcorp rep) stated one-call for road maintanence is complete. blade should be out any time

Excavation will be left open until excavated soil is remediated

* need to check plan again to see what/how samples will be collected from "remediated soils" when backfilled

Released to Imaging: 5/14/2025 7:53:41 AM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Operator: HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX 77002	OGRID: 372171
	Action Number: 461864
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
bhall	None	5/14/2025